Certificate of Location of Government Corner

ID#: 530205 **Description:** SEC COR 2 3 10 11 53 **Date Set:** 10/5/2004 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' south of centerline of driveway
The monument is down 0.5'
Center of grate N 14.35'
This corner is located by GPS measurement

Corner History:

5-20-1854 Michael Karrick, Deputy Survyeor, measured north (Variation 10° 20' East) 80.00 chains between Sections 10 & 11 and set post for corner to Sections 2, 3, 10, & 11. RPs - 14" Sugar Maple S45°W 77 links (50.82'), 11" Ash N73°W 54 links (35.64'), 15" White Oak N35°E 31 links (20.46'), 13" Sugar Maple S85°E 98 links (64.68').

9-29-1884 Thomas Hunter, County Surveyor, (Book A, Page 392, No. 383) found remains of old stake from stumps of bearing trees. Drove new stake in its place not marked. 1/16th North set stake midway and on line at 19.82 1/2 chains (1308.45') to East 1/4 Section Corner.

2-23-1892 Thomas Fraser, County Surveyor, (Book A, Page 470, No. 451) found stake.

7-31-1940 John Kerr, County Surveyor, (Book 20, Pages 62-65) set 1-1/4" iron shaft with parts of broken grate, broken glass, and stone around it. RPs - Part of grate bar set under fence North 14.6'

7-26-1968 John Kerr, County Surveyor, found iron grate pieces and hole where iron shaft had been pulled out. Set 3/4"x30" pipe in hole with iron grate pieces placed vertically instead of flat by pipe with pottery and glass. Set Cast Iron Monument over 3/4" pipe. Set pipe 3/4" on south side witness grate which has short steel fence post by side. RPs - 3/4" pipe N 14.1', Center of grate N 14.3'. The corner falls 3' from south edge traveled driveway. Witness falls 7-1/2' North of north edge traveled driveway. Corner falls 689.15' East of southwest corner concrete mailbox and cream separater foundation which lines with west side of 2 car garage.

10-4-2004 County Survey Crew found Cast Iron Monument down 0.2' with head broken leaning south. Found 1/2" pipe as witness leaning southeasterly.

10-5-2004 County Survey Crew took local ties and removed Cast Iron Monument. Found 3/4" pipe down 2' and took local ties. Ties verified that Cast Iron Monuement was leaning south. Set 5' telspar pipe with Cast Iron Cap over 3/4" pipe down 0.6'. Removed 1/2" pipe used as witness corner and found metal grate down 1'. RPs - Center of grate N 14.35'

10-11-2004 County Survey Crew found Cast Iron Cap on telspar pipe down 0.6' in good condition and measured its position using GPS.

4-13-2007 WHKS Survey Crew found monument in good condition in driveway (poor ties).

7-20-2018 County Survey Crew found Cast Iron Cap on telspar pipe at surface in good condition. Lowered monument down 0.5'.