Certificate of Location of Government Corner

ID#:532106 **Description:** 1/4 SEC COR 20 21 53 **Date Set:** 8/5/2011 **County:** Olmsted

Section: 21 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on east side of CP to fences E-W-S
60d nail in NW side 6" Ash (up2'±) SW 16.7'
Post w/sign 2' west
This corner is located by GPS reference stations "Leaning Outhouse A & B"

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor North between sections 20 and 21. 40.00 chs. Set quarter section post. Black Oak 8 in. N64°W 49 lks. White Oak 14 in. S70°E 104 lks.

2-1882 Thomas Hunter, County Surveyor, (Old Field Book 5, Page 132) used this corner (no description). Set the 1/16th West midway (19.92-1/2 chs.) and on line to the stake found at the Center 20.

11-1883 T. Hunter (Book A, Page 386, No. 377 and Old Field Book 14, Page 12) found the stake not marked, but on testing it by the witness trees still standing, found it incorrect and reset it by U.S. Field Notes from Bearing trees. Set the 1/16th West midway (19.92 chs.) and on line.

11-1939 John Kerr, County Surveyor, (Kerr Book 16 and Book B, Page 542) used the "fence post on south side of lane" as the corner. Measured 2674.1 West to a stone found at the Center 20 and 2628.38 North to an iron set at the NE Cor. Sec. 20.

1-1973 McGhie & Betts did an electronic traverse in Section 21 measuring to a spike set on the North side of the corner post to fences E-W-S at this corner.

2-20-1973 County Surveyor set a 1/2"x2' rod .9 south and .6 East of McGhie's nail and on the East side of the corner post.

7-25-1979 County Surveyor replaced the 1/2" rod at this corner with a square pipe with a Cast Iron Cap. Measured 2625.07 North to Kerr's iron at the NE Cor. Sec. 20 and 2671.70 West to the Center 20 set at intersecting 1/4 lines.

11-26-2002 County Surveyor found CIC leaning slightly and at surface. Set sign and post 2.0' West. Set 2 points to GPS to determine correct location.

8-25-2011 County survey crew found cast iron cap on square pipe leaning. Removed and set a new telspar square pipe with cast iron cap using previously measured GPS coordinates.