Certificate of Location of Government Corner

ID#: 652804 **Description:** 1/4 SEC COR 28 33 65 **Date Set:** 5/22/2006 **County:** Olmsted

Section: 28 **Township:** 106N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The cast iron cap on telspar pipe is down 0.75'
The corner falls 1 1/2' north of centerline of E-W twp road and 3' west of old fence row south
This corner is located by GPS measurement

Corner History:

6-1854 Michael Karrik, 40.00 set quarter section post, no suitable trees for bearings near, therefore erected mound with trench, pitts, charred stake and Osage Orange seeds NE & SW

12-1939 J. Kerr set limestone M&L between section corners.

10-5-1970 Co. Surveyor measured across south line of sec 27 and 28.

10-13-1970 County Surveyor meas from corner post of 40 acres surveyed out for Gilbert Olson 5-1933 B.9 P.6 a large solid steel axle of old spreader placed in cement claimed by son of Olson as spot where J. Kerr set corner. at 1/4 corner dug 4' wide over 5' deep and probed 4' in all directions deep black soil as old road bed over 3' down.

10-20-1970 County Surveyor dug again with tractor on true line between section corners and midway 2638.8, found stone boulder with decided notch on top aprox. size 8x10x18 exact upright position in doubt as stone slightly tilted very close within tenths of M&L so placed exactly M&L. Set original stone N .8', corner slightly south center road and 4' west of fence south. Set 1/2" iron at surface.

6-30-1972 County Surveyor found iron. Set CIM over pipe found below.

1-21-2000 County Surveyor found CIM with head broken off down 0.9'.

5-22-2006 County Surveyor found CIM with two sections broken down 0.9' and leaning east, took local ties and removed. Found 1"x40" pipe in good condition down 2.4', took local ties and removed. Ties showed that CIM was leaning 0.55' east and .14' south. Set 7' telspar pipe w/CIC down 0.55' from ties taken from pipe.

2-16-2010 County survey crew found cast iron cap on telspar pipe down 0.25' in good condition

5-26-2011 County survey crew found telspar pipe with top bent and cap missing. Dug down to the straight segment of the pipe and cut off the damaged portion. The monument is now down 0.75'.