Certificate of Location of Government Corner

ID#: 732604 **Description:** 1/4 SEC COR 26 35 73 **Date Set:** 9/25/2006 **County:** Olmsted

Section: 26 **Township:** 107N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is down 0.6'
The corner falls in centerline of E-W twp road and in line with fence south
County highway disk in S side PP #35851 WNW 97.55'
5/8" pipe S 32.94'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Yerby - 40.00 set temp sec post west on trueline between sec. 26&35 8° 44' east. 40.021/2 set sec post in mound, made trench, planted osage orange seeds N&S of trench.

6-1873 T. Hunter P.228, No. 231, 1/4 corner gone. J.W. Livingston avers org corner is near center of road where we dug.

5-1876 T. Hunter P.293, No.288 found stake P.228, 16west set stake M&L 19.95 (1316.7').

8-29-1968 J. Kerr set CIM over 1/2"x2' rod at location of wood stake hole found.

9-25-2006 County Surveyor found CIM down 0.6' leaning NW, took local ties and removed. Found 1/2" iron rod down 3.3' in good condition. Ties showed CIM to be leaning. Set 6' telspar w/CIC down 0.45' over rod. 5/8" pipe no cap south 32.89' and disc in south side of PP #35851 NW 97.60.

7-14-2008 County Surveyor found telspar pipe at surface w/top mangled. Dug down below bend and cut off. Set new CIC on telspar down 0.5'.

9-20-2011 County survey crew found telspar pipe with cast iron cap broken. Cut off top part of telspar pipe and set a new cast iron cap.