Certificate of Location of Government Corner

ID#: 751905 **Description:** W SEC COR 19 30 75 **Date Set:** 5/16/2002 **County:** Olmsted

Section: 19 **Township:** 107N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and 2' south of fence east
The monument is down 0.7'
CHD in PP NE 36.55'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes Karrick; 80.0 set corner post to section 19-24-25-30. RPs- 14" black oak N5°W 244 links, 13" burr oak S10°W 145 links, 14" black oak N15°E 144 links. Dug trench.

10-1900 W.Fraser Pg.690 No.613; Corner gone, run line W 1/4 30 to W 1/4 19 set stake and 15x15x15 3 cornered stone on line and midway 39.72 1/2 (2621.85).

9-26-1964 J. Kerr set CIM over 1 1/4"x12" pipe. RPs- Fenceline east 2' north of centerline of N-S crushed rock road, disc in PP N57°20' east 36.64', disc TP N38°40' W 84.0' (gone), Measured south 2624.41, also north.

3-31-1988 Olmsted County Survey Crew set 16" CIM over John Kerr pipe at location of broken CIM. RPs- Fenceline east, north 2', County Highway Department disk in PP NE 36.64', centerline of N-S crushed rock road.

5-16-2002 Olmsted County Survey Crew found CIM leaning, took local ties and removed. Found 1 1/4" x 12" pipe down 2.0'. Removed rod and replaced with 5' telspar pipe w/Cast Iron Cap and measured its position using GPS.

1-30-2009 Olmsted County Survey Crew found telspar pipe w/Cast Iron Cap at surface in good condition. Lowered telspar and replaced cap down 0.5'.

2-18-2010 Olmsted County Survey Crew found Cast Iron Cap on telspar pipe down 0.5' in good condition.

5-31-2017 Olmsted County Survey Crew found telspar pipe without cast iron cap at surface bent. Removed bent portion, replaced cap and lowered pipe down 0.7'.