Certificate of Location of Government Corner

ID#: 840709 **Description:** SEC CEN 7 84 **Date Set:** 5/18/2010 **County:** Olmsted

Section: 07 **Township:** 108N **Range:** 14W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" square pipe w/cap RLS #42638

Reference Ties:

The corner falls 1/2' east of elk farm fence corner post to fences north and west and 16' north of centerline of residential driveway
The monument is up 0.2'
This corner is located by GPS measurement

Corner History:

8-7-1953 J. Kerr found limestone with 1/2" steel rod.

7-3-1964 J. Kerr found limestone set CIM over 1/2" x 2' rod by side. Limestone originally set as corner on north side CIM below ground.

8-1998 Mn/DOT Survey Crew found monument in good condition.

3-31-1999 McGhie & Betts found and used CIM.

NOTE: In 2010 County Surveyor determined that sometime between 1999 and 2001 a new fence corner post was set that disturbed the CIM. The fencing crew apparently reset the CIM in concrete with the corner post about 0.5' west of the correct location.

6-12-2001 County Survey Crew found CIM up 0.2' in good condition and was later determined to be in the incorrect location.

9-22-2004 Mn/DOT Survey Crew found monument in good condition.

1-4-2006 WHKS found CIM in good condition. In 2010 County Surveyor determined that CIM was not in the correct location.

7-11-2006 V. Fangman found and used CIM 9 times from 4-29-1985 through 7-11-2006

7-31-2006 GGG Inc. found and used monument at center of section 7.

9-15-2009 Mark Simpson, MN/DOT Crew Chief, found CIM and discovered the reference ties did not fit. He took GPS measurements of the CIM and compared the location with a previous section breakdown which showed the CIM had been moved about 0.5' westerly.

5-12-2010 County Survey Crew found CIM up 0.3' in good condition and determined that CIM had been moved. See 1999 NOTE.

5-18-2010 County Survey Crew removed CIM from concrete around corner post. Found J. Kerr's 1/2" rerod down 1 1/2' in good condition 0.48' east and 0.05' north of CIM in concrete location. Set 1" square pipe w/cap over 1/2" rerod up 0.2'.

11-8-2011 Mike Hendrickson, MNDOT Crew Chief, found 1" square pipe with cap in good condition. Set 2 additional reference ties as follows: 3/4" by 18" iron pin, up 0.1', North, 50.00'. 3/4" by 18" iron pin, flush with the ground, West, 50.00'.