X .6-23-76 found Stone - set no mons - road to be graded
12-27-82 set 1"x 5" Sq. w. Cap 0.20 E. Conc. ✱1
1/4 corner 5 - 8 Elmira 105 - 11. ±510504
5-1875 Hunter P279 no 276 S.8 Julius Kuckenbacher
found stone in center road set by A Cady where orig
stake stood. Meas west 40.04 to see cor stone.
2642.64
10-1897 W Fraser P610 no 555 S 7 & 8 A P K rouse
found above stone 3x5x24 with NW BT still standing.
6" B.O. N 38½° W 392 lks (orig survey BT)
1/16 west set iron stake 20.01½. (1321.0
1/16 south set short wood stake with iron stake by side
M & L 19.99 1/4 (1319.51)
1/16 center NW 1/4 8 set stake with stone 3x6x17 on top at
true inters lines. (over)

1935 Book 83 Page 19 had stone
1935 Co Hwy Dept. Book 75 p3 found 2x6x18 L.S.
sp PP SW 42.2. Lp. 12" pine N.W. 70.6.
sp TP SE 47.1 " Cor F.P. NE 40.4.
Sta .00 going south.
Sta Center 8 2638.6. a large boulder.

1938 Ties found blow mon. Book 83 p.19 Co. H.D.
~~Lp PP SW~~ = PI Sta. 261 + 17.7 Lp - LT 0.34' from South NE 63.7.
~~Lp PP SW~~ Sta. 70.0 ~~Lp~~ Lp TP ~~#72~~ NE 86.2 ✓
Lp 12" pine NW 70.8 ✓
Meas north ~~of~~ center 8 2637.0

Govt Notes 8-1853
Set 1/4 sec. post 40.12 1/2
6" Burr Oak N. 38½° W. 392 Lks. (258.72)

6-1857 E. P. Bircher Road #24
by T. Hunter deputy Meas 40 chs. East to Sec. Cor. 4-5-8-9

#510504 # 2

1/4 cor. 5-8 Elmira 105-11

6-23-76 Dug - found Limestone as recorded 3"x5"x21" with a stake on the S. side 19" deep. Set a 1/2"x25" rod on the W. side - a 1/2"x12" rod at the road surface.

5-1982

R.P.'s Spike in S.W. side 24" Pine NW 71.21 gone

SW corner house fdtn. (top corner) NW 163.66 too long

CSD in pp #1943 SE 64.19 OK 5-25-82

Punch hole E. end driveway culvert WNW 163.05 too long

163.16 to iron set 5-25-82

1/16 cor West

Dug for W. Fraser's iron but it had been cut out.

8-8-77 Tried corner for road grading.

RP Set sq. headed lag bolt 0.1' & road W and in line with West edge of house N W 135.58 your 5-25-82

5-19-82, 1/4 Cor 5-8: Found 5/8" rod, possibly CHDS, bent over. Removed rod and dipped but did not get any further dip. The pine tree with CSD taken in 1976 is gone, but the other three 1976 R.P's are still in place. The lag bolt set West 135.58 in 1977 is gone. We intersected the tie to the SW Cor. house and the punch hole in the culvert. The tie to the pp. SE was appx 0.1 short of this intersection but all come very near the bent iron. Will check location here further with old traverse points.

5-25-82, 1/4 Cor 5-8: Set 5/8" re-rod as corner by angle (137° 44' 39") and distance (857.05) from traverse point #5 and traverse point #3 from 1976 traverse (See Dwg 3-77) Checked tie of 64.19 SE to CSD in pp # 1943 taken in 1976 OK. Corner in ℄ N-S road, 3' So. ℄ rd West, 2' So. ℄ rd E.
More RP's: CSD in corner post NE 70.89
5/8" x 18" rod (2' So. ℄ rd. West) on line to traverse point #5 (8' So. ℄) West 80.10

#510504 #3

1/4 Corner 5-8, Elmira, 105-11

12-27-82, 1/4 Cor 5-8: Set a 1" sq by 5" long pipe with cap .20 East of ℄ crack of new concrete on C.R. 10, from RP's taken 5-25-82. Took no additional RP's