X 7-2-76 Set CIM #512904 (1)

1/4 corner 29-32 Elmira 105-11.
6-1857 Hunter P 33 no 29 S 29.
used orig corner to set center 29.

12-1886 Hunter P 418 = Field Book 14 p. 78
no 407 S 32 L Bauer.
NW BT gone, root & branch, other tree assumed as BT but
unidentifiable placed corner at cor post of fence south.
used fence line south as line for survey.

3-~~1937~~ 1938 ~~32~~ 32? J Kerr B 12 P 51 S 32 for Co Hwy Dept.
run corner m set drill rod N & L ~~2641.25~~ 2639.25
~~22" burr oak S.E. 40.1~~
~~18" " " N.E. 55.5~~ } belong To N.W. Cor. 32
P.B.

1998 Co HD B 10 H P 6. found nothing set drill steel rod M+L 2639.5 (2641.25 earlier)
Lp in 18" br oak W. 149.65 - Lp in F P NE 61.54
- ran line south (random). 5260 ± ?
at area of cedar found dark soil in clean clay as if fence corner had been in place there - meas south could be 2645? ? north 2615
- no description or mention of permanent.

Gov't Notes
Set 1/4 sec. cor. post M+L 40 05 chs.
8" White Oak N 51° W 62 lks.
10" White Oak N 57° E 161 lks.

6-30-76 Dug with backhoe at M+L location for J.K.'s mon. Dug 6 × 3 (9 sq ft) by 4' deep. Area cut to depth of 3½' or more. Found nothing. Line came 29' + S. of fence E.

1/4 Corner 29-32 Elmira 105-11 (2)
#512904

7-2-76 Set CIM over ½"x25" rod as corner midway between the section corner and in line with the main line of fence E. Corner came on Northeasterly shoulder of road approx 22' at rt ∠ from ℄ road and 30' N of ℄ of driveway E and 1'± E of ℄ rod 5.

R.P's: CSD E side P.P. SSW 114.10
W. flange of telephone box SW 72.90
Top center of telephone box NE 73.43
Spike and CSD W. side blazed 6" tree Elm NE 53.10
Center of new corner post E 35.2