X fd. Co. Hwy Dept. iron rod - Bent very Badly - Set CIM over
10-22-1974 on new elec. Survey of Sec. line & prorated.

#610506 (1)

¼ corner 5-6 Dover 106-11

548-1887 Hunter P419 no 408 L6 J Ketchum, H Miller.

Corner missing, comomon land on all sides, no evidence or knowledge of B trees. set temp stake on line and govt prop meas.

govt record. 79.87, actual 80.13 so divided as follows from
5267.46 5288.6
SE cor 6 north 20.08 - 20.08 - 20.08 - 19.89.

- 1/16 south - set stake 20.08 M & L.
- 1/16 north - set stake 20.08 then 19.89 on to section corner.
- 40 chs west to center

North 2638.02
South 2650.56

(over

1939. B101 P9 set 3/4" rod on 1/4 corner on line and. Meas north 2638.5 south 2651.1
E-W fence at 1/4 line lies 6' south of corner as set.
Corner fell in west ditch also. surveyed by A Armstrong and Hellhammer
- P.O.T on section line 1717.6 north of SW cor 5. with RPs
5.6 west center road as surveyed. - Disc in 12" oak W 60.4
Disc in Triple oak NE 69.9
- road alignment centerline 19' east of 1/4 corner.
- PI at 1/16 corner south 1325.6 a hub, with RPs -
Disc in 24" oak NE. 54.9 - Disc in 12" tulum SE 63.7

Oct. 22, 1974 - dug with Tractor Found C.H.D. rod bent over. Set C.I.M. over 1" x 15" pipe on prorated electronic measure on line. corner Falls in west ditch of n-s road 21' ± from center line of road.

R.P's	C.S. disc on east side P.P # 896	S.W.	114.25
	Bottle cap S.W. side P.P #	S.E.	115.37
	Cross in west end concrete culvert	So.	128.1
	center rivet in top west end culvert	N.N.E.	12.67

1/4 CORNER 5-6 DOVER 106-11 #610306 (2)

GOV NOTES - 1855 J BALL

SET 1/4 CORNER SECTION POST 40 chs North of S 6 7 8

TOTAL MILE 1981 526746 - MEAS NORTH 2627.46

BROOK 6 LKS wide South .9 chs 59.4'