X 9-17-73 J Kerr corner removed, entire corner lost. Card #1
9-19-1975 Set CIM. at Corner by T.H. Meas. from W. & T.F. from South
10-21-83 Set C F Clip 27-18 Dover 106-11 #G10705
Section corner west 12-13 Eyota 106-12

12-1890 2 bx Fraser P450 no 434 d 18 Corkerall-Leighmen
found boulder 6x10 x16 said to have been placed at exact
location of original corner. no measure.
Placed by Hunter 1875 P281 no 278 in place orig stake

6-1900 R Fraser P686 no 610 d 8 Gw Huff & others.
found boulder (previous survey) in locating SW cor 8
2 miles over ran govt meas 16 links

4-23 & 6-30 1952 J Kerr B53P70 for REA Town line required.
found part of recorded stone placed 1" x 39" pipe stone by county
Spud. PP NE 49.7 – Spud tile P SE 35.4 – Spud tile for SW 39.8
assumed line south #11 used Highway notes.

COVER

9-11-73 found J Kerr pipe badly leaning due to wet soils and RPs all gone corner known to be wrong so removed it as found. dug entire area west and north - ran in line from west and south. poor records.
9-17-73 dug again further west and north area very wet and hard if any below wet muck - Corner lost. No sign even of stones found by J Kerr 1952. 1/4 E 13 west also lost dug entire road. Corner must be set by lines occupied and mean of 2 meas from west and 2 south. see field notes.

Gov't notes: Sept. 1853
Set Post, drove charred stake, built mound with trench

7-11-75 dug S.W quad of intersection with backhoe but found nothing.

#610705 Card # 2

Section Corner W 7-18 Dover 106-11
E 12-13 Eyota 106-12

9-19-75 Set C.I.M. over 5/8" x 18" rod in 4-Way intersection in ℄ E-W road and 5' W of ℄ N-S road. Set by T.H. meas. from W and T.F. measure from S.

R.P.'s CSD in pp# 11 NE ~~52.46~~ 52.37 7-80
CSD in telephone pole NW 38.14
CSD in telephone pole SW 51.47
Punch hole in N. end 24" CMP to road W. NW 34.92
Punch mark in lug at S end 24" CMP to road W SW 33.80
CSD in brace post to fence W on S. side of road W SW 64.18

4-13-1979 Found CIM OK!

7-16-1980 (1980 Lemon Book) West 7-18: Found top two sections of CIM broken off. RPs indicate the bottom piece has been pushed slightly West. Reset the top piece at the intersection of R. Ps. All ties agree well except the CSD in pp # 11 Now NE 52.37 Should dig out and set new CIM over rod beneath broken CIM

10-21-83, W 7-18: Found piece of CIM set 7-16-1980 tipped over. Dug down to rod and found nail set beneath CIM in RPs RPs in 1980. Nail was .02E of Re-Rod. Drove 4' Telespar with a Cast Iron Cap over rod as usual

RPs: C.S. Disc in pp # 11 NE 52.48

C.S. Disc in telephone pole NW 38.06

C.S. Disc in telephone pole SW 51.38

C.S. Disc in brace post to fence line on the South side of the road West SW 64.12