~~6-15 1961 C/M set by County~~ B240P5 ①

10-25-79 CIM 12-27-82 set 1"x5" square w/cap 2.88 W. ℄

section corner 27-28-33-34 Dover 106-11.

No records of any kind. #612705

county had 1/2" ~~rod~~ (origin unknown).

set C/M - 8-1961

Disc	power pole		SW	~~58.98~~ 58.84
"	"	"	SE	~~63.05~~ 62.93
"	tel	" #521	NE	~~67.75~~ gone 7-1976

COHD B180P78

set corner midway from section corners N & S 5259.9 and on center ℄ N-S road. no line other than center roads. Disc in RP SW 42.52 - Disc FP NW 79.95 Sp PP SE 44.8

(OVER

Meas - east 52526
set 1/2" rod as Corner (as set)
- south

B 240 PS CoHD 1961. set CIM in place of corner
Meas. north 2633.2 To 1/4 Cor 27-28
Δ 0° 2' 1/2' Δ Lt 0° 07'

9-1935 C.H.D Book 83 page 24 use something for Corner

7-76 Found 120d spike at road surface on CIM.
Removed spike and set a 10" CIM over
the CIM in place. Corner in ℄ of roads
N-S-E and 3 1/2' N ℄ road W.
Add. RPs: Punch hole top N end 16" CMP to
road W NW 34.47
Punch hole S top end 16" CMP to road W

GOV-NOTES - 1853 - J BALL - SET SECTION CORNER post 80 chs North of south 33-34 SW 38.95

#612705 (2)

Section Corner 27-28-33-34 Dover 106-11

10-19-1979 Jackhammered a small hole on the SW side of the CIM to check conditions before digging with the backhoe. Found much more fill than expected so will dig with backhoe.

10-24-1979 Dug 1 bucket width with the backhoe from the West side of the CHD monument South. We found 2½' of fill on clean clay so we dug no further.

10-25-1979 Set a CIM over a 5/8" rod 3.93 So. and 3.34 W. of the C.H.D. corner (removed). This location chosen N-S at the center of roads E-W as found by the CHD in 1935 (Kalb Book 83)
1935 Alignment shows Kalb set Sec. Cor. here 5253.1 South of Sec. Cor. 21-22-27-28. 1935 Topo shows center

Rds. E-W 5664 South of Sec. Cor. 21-22-27-28 or 10.9 So. of Kalb. In 1943 A. Armstrong (BK. 180) reset this corner 5259.9 South of Sec. Cor. 21-22-27-28 or 6.8 South of Kalb leaving 10.9 - 6.8 = 4.1 to center road. After setting up this point it came in the center of the road West (the road East is graded to Armstrong's corner). This point also comes on line from the C.H.D. corner in the center of the road at Sec. Cor. 26-27-34-35 over the stake found at the 1/16th West. The location chosen E-W at double the measure from Armstrong's hub found at 1/4 Cor 27-34 (said set in line with fence So) over the stake found at the 1/16th West. Corner in ℄ road West, 4' South ℄ road East, and 3½' West ℄ N-S road.

RP's: CSD in North side power pole SE 63.64
CSD in NW side power pole SW 53.93

Section Corner 27-28-33-34, Dover, 106-11 #612705 (3)

5-26-82, Sec. Cor 27-28-33-34: CIM appear to be tilted West. Checked tie taken 10-25-1979.
RP: CSD in North side power pole SE 63.69
(63.64 - 1979)
CSD in NW side power pole SW 53.87
(53.93 - 1979)
Ties indicate CIM leaning W'ly .05 to .06.

12-27-82 Set 1"x5 square w/cap 2.58 west of Concrete ℄. Took not new R.P's.
Corner falls 3.08 west and 4.10 South of the CHD P.I. line. Set corner from RP's taken 10-25-1979