X 5-11-1970 set C/M ones iron rod. glass stones found #620805 rock. (1)
section corner 7-8-17-18 Eyota 10 6-12
5-1877 Hunter P310 no 304 L8 Mike Cassidy, etal
found "pole" avered by cassidy and others as true corner.
B trees gone, accepted corner as is, set stake in place.
— 1/16 north set marked stake M & L 19.67 1/4 to stone at
W 1/4 8 tested by meas of 92 lks south of L KR tracks.

6-1893 H F Fraser P512 no 480 L18 Sullivan, J Campbell.
found corner P310 - drove iron stake as corner, lines
with fence west -
— drove stake 80 rods south also
— drove stake 35 rods south of above stake. over)
— meas south to 1/4 corner stone set M & L 39.83 1/2 (2629.1)

10-1930 J Kerr B4 P10

found iron in line fence west → only copying W.F. here but he did use something

Meas south to E 1/4 18- 2626.29. rough line.

10" blazed oak - N 38° E 58.5 blazed at root & 5' up

~~12" " " N 76° W 5.2~~ only stamp 8-7-68

did not set C/M at this time

8-7-1968 found square bridge bolt at corner in dug pit 18" deep

10" bur oak bore 18" 58.2 to nail in blaze (head of nail) N 38° E

Center of number plate 15881 on power pole N W 81.8

this bmeas knee high at corner to plate on direct slope

head of nail in tall corner post of fence west which is in line with corner as the fence runs west W - 30.4.

Disc on E side power pole No 15880, badly shot up - SSW 131.55

5-11-1970 to surv - set C/M. over bolt glass stones.

set steel post just north of C/M.

(2)

620805

Section Corner 7-8-17-18 Eyota 106-12

Set by William Jones 9-1853

80.00 Set post at corner to sect. 7, 8, 17 & 18

Br Oak 8 N 89 E 40

Red Oak 6 N 10 W 19

Br. " 5 S 45 W 46

Br. " 7 S 15 E 64

4-4-77 Set a CIM over the CIM in place. Corner on East bank of ditch on West side of turnaround at the intersection of roads East and South. Corner 7' West of ℄ road So. and 7' So. of ℄ road East. and in line with the fence West

R.P.'s C.S.D. N. side pp # 42544 ESE 108.70
CSD W. side pp # 42484 SSW 132.80
CSD S. side corner post to fence
S-W-N W 30.43

5-7-1883 T. H. (Fieldbook 14, P. 3) measured 79.86 from SE 18 to line of board fence running West at NE 18. NE 18 missing they having plowed and scraped the road and totally destroyed all evidence of it.

10-1930 John Kerr (Kerr Book 4, P. 11-18) "tried for NE. Cor 18, didn't find it." After he found SE 18 and E ¼ 18 he measured E line 18 and used something here (no description) To set ¼ Cor 7-18