X 9-24-1968 set CIM over 3/4 x 12" rod. #622005 (1)

section corner 19-20-29-30 Eyota 10 6-12.

5-1882 Hunter P377 no 368 L20 John Hughes-E Cornwell.

corner missing, no evidence. two B trees standing would not place corner anywhere near where it was known to have stood, even mean alone was way off.

Meas L 1/4 20 to L 1/4 19. 79.84 set midway. and by measure from L E B T which brought corner in line fence west anered by John Hughes as set from corner.

- placed stone with burr oak stake by side
  Burroak N57½E 95 lks = 62.7 Burroak L46°E 84 lks = 55.4A

- 1/16 east set stone 2x10x19 M&L. 19.96.

- meas north to 1/4 19-20 39.94½ set M&L. (boulder)

6-1883 Hunter P384 no 375 L19 John Hughes (over)

used corner marked stone - Meas west 39.92 to S 19 1/4 07.

6-1913 D Williams P 222 B S 19-30 Town Board.
found limestone - tested by Hunters B Meas. correct
Meas south line S 19. 3892.5 to start of road
around detailed lay-out see 1/4 19-30.

1945 Co Hwy Dept B126 found hard head & strap iron
Sp 12" Ironwood NW 35.0 — Sp 15" Maple SE 72.96.
Sp 18" Oak NE 63.43 - Sp 6" pole NW 49.78

1961 Minn Hwy Dept line center all roads.
Dice PP NW 48.95 - Dice 24" Oak SE 54.95 Probably orig. B.T.
~~Dice 20" oak stamp NE 63.6~~ Let CIM 7-2468 J Keir.
1/2" rod up 8" - 4" north E-W woven wire fence SE 100.00

#622005 (2)

Section Corner 19-20-29-30 Eyota 106-12

Set by William Jones 9-1853

80.00 Set post at corner to sect. 19, 20, 29 & 30

Br. Oak 7 S 43½ E 84

Br. " 7 S 83 W 111

Br. " 6 N 55 W 92

Br " 5 N 4½ E 760

6-15-78 Dug from the CIM West 3½', North 3½', South 3½'. Found 3' of fill over 4" clay (which looked like it had been driven on) over bedrock. The cast iron was set over a 3/4" x 12" rod beside a 5" long eyelet and

iron stake driven in bedrock with a 2½" x 10" x 7" stone standing by its side.

RPs: MHD Disc in pp # 15623 NW 48.91

MHD Disc in NW side 28" Burr Oak SE 54.92

½" rod (up 12") on N. side ~~28" Burr Oak~~ fence E ESE ~~SE~~ 100.0

Corner in ℄ rds. S and W

The Burr Oak standing SE is possibly the original SE bearing tree.

5-14-79 Took more RPs before road construction

Set a ½" x 2' iron (.5 N of Survey Marker Sign and Post) 149.98 East and on line to ¼ Cor 20-29 (Found in good condition)

#622005 (3)

Section Corner 19-20-29-30 Eyota 106-12

6-7-1982, Sec. Cor. 19-20-29-30: Found a 3/4" iron at road surface (possibly C.H.D.) Removed and dug ~~ed~~ CIM rather turned out to be only the bottom 6". Found 3/4" iron beneath monument but not centered under CIM (don't know if the iron ever was centered or if CIM displaced when hit). Will reset from MHO Disc in pp # 15623 NW 48.91 taken in 1978 and the 1/2" rod set 149.98 East on the section line in 1979. The Burr Oak tree SE was destroyed in construction and so is the 1/2" rod ESE 100.00.

CHD 3/4" iron } 1.83 E / 1.6 S CIM } 1.83 E / 1.94 S 3/4" iron under CIM } 1.66 E / 1.78 S

7-8-82, Section Corner 19-20-29-30: Removed 3/4" iron, flat iron, eyelet and small piece of limestone and set a CIM as the corner on the line from 1/4 Cor 19-20, ~~and~~ over the iron set 149.98 East on the section line ~~at average of distance from sand iron and tie to pit NW~~ in 1979 and ~~V 149.98~~ from sand iron. Bedrock too close to drive iron beneath the CIM. Corner in ℄ road West and in ℄ road South and in 42' NW'ly ℄ road on curve to NE

RP: CSD in W. side pp# 45619 NW 38.64
MHD Disc in W. side pp# 15623 NW 48.85
1/2" rod on Sec. line E 149.96

8-23-95 FOUND 3/4" IRON SET BY C.H.D. FROM REF PIPE W/CAP 3-1994