10-17-75 Set CIM
9/1/88 RESET CIM FROM (1975) TRAV. PTS
#623604 ①

1/4 Corner - S. 1/4 Corner Sec 36 Eyota 106-12
N. 1/4 Corner Sec. 1 Orion

No records, except that T. Hunter apparently used this Corner To locate Section 1, Center Section in 1857 Survey.

Dug with Tractor 10-7-1975 but road was worn down To clean Clay about 1½' below present road. Fields To S.E. & N.W. indicates road was on sharp ridge & apparently got cut out or worn out.
Will place this Corner on Sec. (Township line) & in line with fence To South and also on line of N. 1/4 36 over fence near Cen. 36.

10-17-75 Reset C.I.M. over a ½"x18" rod at the intersection of line from N ¼ 36 over fence at Center 36 and line from NE 36 to SW 35 Corner falls 4.5' North & of E-W Twp road and in line with trees N and S.

R.P's

CSD N side pp # 1877 NW 122.59

Spike & CSD W. side of westerly twin 18" Burr Oaks N 112.7' (USED)

CSD in E side 17" ~~Spruce~~ Cedar S ~~43.93'~~ 43.50

Gov. Notes 1853 Oct. Ball, Dep. Sur.
West between 1 and 36.
40.00 Set quarter post.
Br. Oak 6 in. N70E 57 lks
Br. Oak 10 in. S42½E [redacted] 154 LKS.
46.84 Brook 4 lks. wide runs S. W.

(2)

¼ Corner S. ¼ Corner Sec. 36 Eyota 106-12
N. ¼ Corner Sec. 1 Orion 105-12

#623604

4-16-81 Found CIM O.K. Shot corner.

9/1/88 FOUND CIM GONE FROM 1982 ROAD GRADING
ONLY TIE LEFT WAS SPIKE & R.S.D IN 17" CEDAR, RESET
FROM (1975 TRAV POINTS) TIE TO 17" CEDAR SOUTH
CHANGED TO 43.50'