#641509

8-27-1963 set C I M over pipe
C I M broken reset 6-12-1970 (1984) CORNER DESTROYED

1/4 corner Center 15 Rock 10 6-14.

11-1892 Hunter P 210 no 218 L 15 J M Westfall.
had all 1/4 corners - no mention of setting center but
1/16 west. set stone 2 x 8 x 15 M & L. 19.96

1936 Leonard P 460 B L 10-15 H Lillis
set 7/8" drill steel 1/3 distance from 1/16 west to 1/4 14-15.
this rod in east ditch of road. ~~13 22.16~~ (now probably 13.17 ± west)
13.16 C Keir 1984

~~spike in PP E S E 12.16~~ (1970)
" " 24" elm ~~E 22.7~~ blazed 44.88 to head of 120 E
~~" " 15" oak NE 66.8 "~~

Correct Keir Cor ± 5' W. of This Rod

rod found & preserved, used many surveys. Change in Cen. 15
8-1963 set CIM over pipe. 10-29-1940 Book 22p 44
- Spike in power pole SE OK 21.43
- ~~punched cross~~ Chisel cut edge east end Metal culv. N 41.7 ~~19.26~~
- corner now out of ditch in east edge traveled road.
- 16 east. found drill rod at 1323.07
- south 1¼" pipe at SW cor prop corner. 1180.5 or
2625.0 south to ¼ 15-22.

6-12-70 CIM brought into office broken & found in ditch - found ½" x 12" pipe in place and found orig pipe below. Reset CIM. down 7" below road.
orig 120 D in huge elm 8' south of east, head nail. 44.88
punched cross on west end 36" rod culv & NW 66.13
corner now lies some 3 or 4 feet west of E edge road.