#642309 (1)

6-25-1964 set C/M over 3/4" x 12" rod.
6-2-1980 Reset 16" CIM over 3/4" above 3/4" rod Fd in place

1/4 Corner Center 23 Rock 106-14.

5-1874 Hunter P250 No 251 S 23-24 J Easton
H & D Smith.

set stake at true inters lines.
-16 east set stone 2 1/2 x 10 to point x 16 M & L 19.85.
- meas south 40.08.
-16 west set stake M & L 19.89.
-16 north set stake M & L 19.93
-16 center NW 1/4 23 set stake at inters of N-S 1/16 line and 1/16 line east to east line 23

---

5-1895 2r Fraser P 566 No 519 S 23-24 J Easton
found stone set in place of stake P250 by Fred Smith Cover

16 east found stone set by Hunter M & L 19.85
–16 north set stone M & L 19.90

---

limestone 4 x 8 x 20 found pipe set by side as witness.
6-1964 set C/M over 3/4" x 12" rod. (6-2-1980 found 1964 C/M broken

– org stone up 1.1' west 0.7'
– 3/4" pipe in fence up .8' S. 0.3'
lag-screw blazed 20" oak. SW 64.4
Center " 24" " S 113.2
lag screw N edge blazed 20" oak SE ~~61.6~~ 61.53

6-1980 RPS checked SE & SW Ties. Corrected SE Ties as Shown Took new RPS Control disc in RR East – 20.01 Top Center 12" Sq. Tel. Box – S. S.d. 268

corner lies 1441' ± west-center & north bound lane #63
property corner-stakes on West RW 63 and 750' west.
1968 run line south set rods at 933.0 and 1233.0 total 2637.08

1/4 Corner Center 23 Rochester 106-14 (2)
#642309

6-2-1980 (1980 Remon BK. Page 49) At Center 23: Mc & B reported that CIM was broken and that bottom section of monument laid on top of ground and top part was set in position nearly correct. Stone and pipe references are now gone. Drove to site of monu. and found Mc & B report correct. Dug down to 3/4" x 12" rod set by Ken under original C.I.M. Checked B.T. ties and found iron rod nearly correct but did not move it as it looked undisturbed Set 16" CIM on 3/4" rod which makes top of CIM flush with surface of ground. - Placed steel fence post on N. side. Took add'n ties
CSO in new PP. East 20.01
Top Center of 12" sq metal tel. Box SSE 26.8