8-16-1965 ~~set C/A~~ required above iron bar driven #740909
down, this bar being accepted as true corner.
3-29-1973 found stone as True Corner. Reset with 1" iron ①
1/4 Corner Center 9 Cascade. 107-14
set 3-14-75
4-1870 Perry P108 no 147 S 9 & 10 M. Clark.
~~set~~ found stones at true intersecting lines.
-16 North set stone M & L 19.78 (1305.5
-16 south set stone M & L. 19.78 (1305.5
-16 east set stake M & L 19.94 (1316.04'

5-1911 Chas Larson. P166 B S 9 & 10 J Pennington.
found limestone down 4' set boulder 2x6x24 on lip
at surface.

1919 C.H.D Book #29 Page 46 found stone

(over)

1" iron bar set in bottom deep ditch on east side
set by Mc+B in 1950's
concrete highway 52 (now abandoned as arterial highway.
8-16-65 ~~set C/M~~ removed in 1973 over same 1" rod driven down.
crushed rock placed in hole on top C/M.

Corner lines with fence east

- Angle iron corner post east of corner E 13.0
- Nail in center old pavement straight W 40.85
- Center east end conc culv under pav. NW 46.0.

4/4/90 FD McGhie PIPE IN ROAD DITCH EAST OF PAVEMENT SET STEEL POST ± 1.0' EAST

Card # 2. Center 9. Cascade · 107-14 #740909 (2)

history of 1" iron bar found when CIM set 8-65
- set by Conne Fossum & McGhie by Highway data.

3-29-73 Mr Tom Taylor claims corner stones he S & E of CIM in place. As corner stone recorded as 4' deep P166 B book. by Chas Larson who found limestone and placed 2x6x24 slug and probed and found both stones 2.0 south and west of CIM - removed CIM and iron bar below and set 1" x 4' iron bar centering ones stone.

46.03 E to bend on N side 20" walnut close to ground.
14.12 2' N & E to corner angle corner post
23.03 W & south to .3' in. north end drive culv in plange lug
30.2 W to ~~East~~ east edge concrete road.

10/27/78 Found a 1" iron rod @ Center 9.
Waterman being installed will take out corner monument.
Took new ties:
60d in tree ESE 46.14
Spike in E. side p.p. NNE 58.75

2/24/84 Fd 1/2" pipe (5/8") with platic cap # 11622
60d in tree ESE 46.02
Spike in E side pp (now bent) NNE 59.40 } roughly taken
Note reference not the same as 1978.

1-1985 Info From McCabies: Pipe set in 1981 at intersecting 1/4 lines (some of work based on T Taylor work)
RP's 60d spike in 24" oak ESE 46.13
spike in E side p.p. NNE 59.48
& Paint crack W. 39.97
Dist. from center to So 1/4 Cor 2608.33