9-9-1963 set C I M over 5/8" x 14" iron rod. (1)
Note: CIM removed by someone (4-24-1978 reset 16" CIM over 5/8" ~~rod~~ rod)
1/4 corner 12-13 Cascade 107-14 #741204
6-1900 Robt Fraser P646 to 652 No 582 S 1-2-11-12.
found stone stacking 4" above ground, 3" thick averred.
by Mr Makon to be correct corner in line N & S fence.
-16 west found stake anered by Mr Regal as stake
set by Hunter no meas.

3-1902 R Fraser P32B S12 J Baker, L Greenwood.
found corner above P646—
-16 north set stake M & L 19.92 (1314.72
then 7.47 chs then 12.45 chs

2-1878 Hunter P330 No 324 S13 O Brooks.
found old stake standing in fence, replaced when found 1/2 not meas.
survey No 89 Aline fences N & S.-found 1/10 west fence

4-1931 J Kerr.
run line N between know corners Center 12 and S 1/4 12.
set iron corner at M & L. 1316.05

1948 J Kerr
run line West. set pipe as 1/16 corner M & L. 1313.92.

1963 J Kerr removed stone set C I M over 5/8" x 14" iron
Sp in 14" hickory S W 22.6 } gone in April, 1978
" " 15" W Oak N W 46.0 }
corner lies at fence corner, just south of post.
west to U S 63 ~~several hundred feet.~~ ± 300' E. of ℄ Hwy

4-24-1978 Co. Surv. - found Lower 5/8" rod (down 18") Set 16" CIM over Rod

R.P.'s
S.W. Cor. of House To N.W. — Slope meas. = 95.75
S.E. Cor. of " To N.N.W. — " " = 86.85
(3.75' So. & 0.5' W. of MN/Dot Trav. Al.) S.W. Cor. of House To N.N.E. - Slope Meas. = 112.0
corner ± 300' E of T.H. #63

#741204 (2)

¼ Cor 12-13 Cascade 107-14

4-1978 Received survey data from MHD. Filed in "blue book." Calc. measure West 2626.32 to CTM (at Center 13) East 2636.43 to CTM
South 2627.66 to ½" rebar

Survey has coordinates on all corners in Section 13 except the SE Cor.

Co'l Notes on Knoll 185'↓
40.00 S+E from ¼ sect post
West on trace line between sects 12+13
40.00 S of ¼ section post
White Ork 10 S 30 E 300
White Ork 12 W 25 E 400

V 6° 31'

(over)

Oct, 1859 T. Hunter Pg. 63 No. 89 shows 1/4 Post
1/16 North 20.13 chs., 1/16 South 20.08 chs.
(See Survey for breakdown in S.E. 1/4 12 & N.E. 1/4 13).
B.T.'s to 1/16 North (6" Beech N 26 1/2° W 56 lks, 10" Beech S 27° W 22 lks.)

8-15-83, 1/4 Cor 12-13: Found CIM set in field in 1975 - now down only 3". Removed CIM and drove Telspar with CIC down over iron Post beneath CIM. Top of CIC down 2'. Nothing to tie to. Post with dia tacks in it has now fallen over.

8-15-83, 1/16 E: Found pipe down 2" in old E-W road but top appears bent East. Reference tree SW now only a stump. Reference tree SE OK. Purpose of survey was to stake section line to regrade E-W road on the South side of the line. Both corner and reference trees could be destroyed in road grading.