6/30/83 SET C I.P. over 5/8 rod 6-22-78 removed C.I.P.

~~9-27-1961 Set C.I.P.~~ over iron. #743006 (1)

section corner. west 30-31 Cascade 107-14.

east 25-36 Kalmar 169-15

9-1874 Hunter P260 No 259 NE¼ 36 Sterling Cross

found remains old stake. set quarry stone into place.

- west stone marked on plat at 20.00 and 40.00

- south. staked out 1 acre adjacent to RR track 875' south then 100' to North R.W. and 226½' west.

---

12-1921 J Kerr P 3-14 B S 31 Sisters of St Francis

found stake by mear from S R.Way. 1033'

set stone 4x5x19 and pipe.

over)

east — bearing of line east S 89°38'E ~~south~~ N 12°W.
1/16 east set corner at prop dist. 1171.7 then 1358.4
to 1/4 cor. limestone 3½ X 17. + iron pipe with
post 1' south - 1297' from ℄ RR track on ~~line~~ west.
~~Hunters notes~~ - also 988' " " " " ~~north~~

B 84 P 23
meas east to
N-S fence 2528'

9-1961. Iker corner used many years
replaced stone with C/M over iron pipe
SE corner. school house. NW 134.6.
~~SP~~ power pole ~~B335' SE 5.4 60~~ SW 92.6
" tele pole NE 39.65
~~Cont to Sta 184 to 3+80 B335 1468~~ See card 2 ~~Meas north 2631.65~~
to 1870 Perry P 120 N 155 S 36. found stake near ~~north~~ 263725
from orig mpremonsurvey - SE cor S House N 41°50 W 2.32.
set 1/16 corner west.

[#743005] (2)

Card #2. west 30 - 31 Cascade 107 - 14.
east 25 - 36 Kalmar 107 - 15

Co H-D 1968 B 335 found C/M. Sta 184+63.8.
Add RP. Lp O power pole L E 54.60
Meas. south 2631.65 Meas north 2637.95

Meas south To center line of east bound lane. 1301.± angle at this point in highway north to east 50° 28'

---

6-22-72 removed C/M. set ½" x 2' rod.
122.0 NWly on Ag to Tower SEly to 120 2'± E of small tree.
96.25 WNW to E edge tub bell post




---

6-1936 C.H.D. Book #81 page 24 Found limestone monument with pipe under it. Set by C.H. Armstrong 1921

April 1, 1863 R.C. Compton Pg. 72 No. 103 shows Sec. Cor.
(See survey for breakdown of Sec. 25

[illegible]

---

6-30-83, W. Sec. Cor 30-31. Set a CIM over a 5/8" re-rod on Roger Brandt 1972 Az Tie — on line between KROC Town and 120d spike 122.0 NW'ly and 122.0 from said spike. Found several spikes as we dug down at corner and found a 5/8" re-rod down 14" .28 South and .20 West of cor. as set — removed rod. Dug down about 2' and had a dip in the hole but could not get down further (small jackhammer hole)

(Continued)

(#743005) (3)

West Sec. Cor. 30-31, Cascade:
East Sec Cor 25-36, Kalmar:

Local RP's E 2.79 S 3.05

6-30-83 continued:

RP's:

Spud in N. side power pole SW 92.75
Old CHD Disc South side pp NW 90.77
Plastic CHD Disc in North side pp E 44.89
Corner in ℄ N-S road and in ℄ road W.

Old school R.P. now unreliable (New siding and cement around foundation)