#743209

1/4 corner Center 32 Cascade 107-14.
6-1970 corner unknown.

1894 - W.C. Fraser - Set Temp. Stake at Center Section by intersecting Lines.

1957 - K. McGhie - Set 1¼" pipe on E-W ¼ line & from S. ¼ Cor. To fence line near N. ¼ Cor.

JAN. 1994 Co Surv.

Found pipe leaning S.W. very bad. Reset the pipe from a rod set by Mc-B 458.50' E. - the W. ¼ cor. 32. for N-S. control. For E-W control we used the meas'd 458.50' E. to rod set on E-W ¼ lines by Mc-B at 458.50'. We then pushed the line North to set the N. ¼ cor Sec. 32.

The 1/16 cor. South Cen. 32 is now slightly out of line between the S 1/4 cor. Cen. 32. Center Sec 32 falls out in an open field west of Country Club Manor - there are no R.P.'s to this corner other than meas E. - W. - N.

Nov., 1856 Thos. Hunter Pg. 19 No. 31 shows Center Sec. Meas. South 39.30 chs.
Center S.W 1/4 meas. West 19.52 chs. & South 19.67 chs.

Mar, 1857 Thos. Hunter Pg. 23 No. 37 used Center Sec. 1/16 North 20.04 chs. M&L, Meas. West 39.33 chs.