X

#750406

(1)

1/4 corner 4-5 Kalmar 10 7-15.

1-1870 Perry P95 RO 139 SE1/4 S5

used corner - set stake west 10.00 then 8.75

11-1916 J Kerr P 260 B. line 4 & 5 Searles, Carlson. Ironboard.

set stone and broken glass arround it on line at prop distances from N W cor section 4.

-1/16 south stake 1310.52 M & L

-1/16 north set iron stake in broken glass 1310.52 then 1305.93 to iron stake & bolt at NW cor 4 neg.

see N 4-5. 1303.8 in 6-19-1970 when found & referenced

as 1/4 cor 4-5 set stone in glass.
60D 8" pin oak S 50° 30' W 11.61'
60D 10" pin oak S 23° 45' E 7.5'

1947 J Kerr. B 32 P 62 line betw 4-5 for Kalmar T.B.
found stone in dry wash lying flat.
reset from. SE witness tree with 3/8" x 26" rod.
60D in 14" pin oak S 23° 45' E 8.' (both in 6-19-1970)
60D in 18" elm east 8.
Meas north 2613.57. 1916 2616.45
" south 2618.4 " 2621.04 with points between

6-19-1970 J Kerr corner found also 1/16 iron. north ~~see~~ S 32-33 N. Haven - line from N 4-5 (also found one 1/16 iron missed 3/8" rod. on east side rod about .2' or very close. both oak & elm tree in good shape. rod in wash but new road helped some corners, willnet C/M.

Kalmar 1/4 corner 4-5 #750406 12

Set 18" Pin Oak 8" dia 1/4 post

5 links West from 1/4 post between Sec 4 & 5

White Oak 8 S 50 E 75

8 S 44 W 50

Dec 1856 Thos. Hunter Pg. 20 No. 32 Shows 1/4 Post.

Meas. South 39.89 chs. to Sec Corner

1/16 East 20 chs. M & L B.T.'s (N 33° E 40 lks. & S 15° W 53 lks.)

Note: 1/16 East Stands in River and a stake stands on the Bank 50 links North of the 1/16 Sec Post.

7-31-85 RP's to re-set @ 1/4 Cor 4-5 From Vince Fangman

Lod in 18" Pin Oak SE 8.09 7-7-95 R Beard could not find nail

8d in 12" Pin Oak WSW 30.70 7-7-95 Gone

8d in So side twin Elm ESE 8.43 7-7-95 Could not find nail

7-7-95 Roger Brand and Assoc. found 3/8" rod in shallow small ditch running South. Set 5/8" pipe over 3/8" Nail with green disk in 15" Elm (ESE) 8.1 feet
Nail " " " " in 18" Oak (S) 7.8 feet
Corner 2 feet North of fence line East
and 2' South of Hyde fence Northwest