1 4-7-75 Set a C.I.M. over a 3/4" x 10" rod #751204 with mons. set 10-12" below ground surface (1)

1/4 Corner 8-15-83 Replaced CIM into CIC/P 2-13 Kalmar 10 7-15.

6-1870 Perry P122 No 157 S12 C Grassley.

found stake in mound with pits plain.

set stone 5 x 5 1/2 x 19 and old stake by side. 1319.34

- 1/16 east set stone and stake 5 1/2 x 5 1/2 x 17. M&L 19.99.
- 1/16 north set stone and small stake 4 x 5 1/2 x 18 M&L 19.99. 1319.34
- 1/16 center S E 1/4 12 set stone 4 x 5 x 23 with oak stake M & L 19.98 1/2 on N-S 1/16 line. 1319.01

1/16 N found 12-3-71 as recorded.

(over 1/16 west)

Co Hwy Dept. 6-1961 CIM B 244 P2 1/16 cor west.
found stone (no records or meas on this line)

Hub NW 78.27 Sp cor fence post NE 57.21
" NE 82.02 " " " " W 65.17
" SE 85.0 3661.95 N from intns #3 #4.

6-1961 set CIM. W7-18 at E12-13

12-3-71 on reconstruction search for corner data meas from nail in center cross roads (old road west) To corner of fence at 1/4 12-13 area - about 2642 to corner post set 1.20 D at 2638. - believing this fence west to be north road fence proceeded to meas north to find 1/16 stone, found 4"x5 1/2"x18" L stone in clean black soil just west creek some 20'± N of post with old brace wires at 1294.45 R1319.34 set old oak post on N side of stone with red cloth on wires (look up to 25'S of Cor Pfm 14 12-43.

#751204

Card # 2. 1/4 12-13 Kalmar 107-15. (2)

6-5-92. dug entire area where corner should be, now in cultivated field. - ran N-S 1/4 line Sec 12 on a 50' offset west at 1/16 North and CIM at 1/4 1-12. line corrected fell exactly on fence terminal at S. 1/4 12.

6-6-92. found 1/16 stone east as recorded. 5½ x 5½ x 17. lying tilted west but found exactly where stone base was. - seems mean east about 13 20 west up to 1324+. May run line & zap after setting E 12-13.

#751204 (E)

1/4 cor 12-13 Kalmar 107-15

4-7-75 Co. Surv.

Dug again through the frost for the stone set by R. Perry after doubling the line + distance from the S.E. cor Sec 12 West over 1/16 stone found 1819.89' West of S.E. cor. Set a C.I.M. over a 3/4" x 10" iron rod. Doubled above distance + line to set the corner. Corner falls 26' South of the fence West + 4' E of the of the fence North

R.P.'s

C.S disc in S.W. side oak post in fence running West (Knocked over) N.W. 42.1'

C.S disc on E. side oak cor post N.N.W. 26.7 (in place)

8-1983

1/16 cor. E 1/4 Cor 12-13 Dug down and found 3/4" pipe ~~found~~ set in 1972.

R.P.'s 20d on S.E. side Hickory (?) S.W. 50.1'
20d on S.W side 24" Oak S.E. 42.8'

Govt Notes Kerr ck 1854
40.00 set temp 1/4 set post
West on true line between set 12+13 V.C
40.00 set 1/4 set post in mound with
trench, pits, charred stake + Ostyc
Quarry scale NE 1.5.W

8-15-83, 1/4 Cor 12-13: Found CIM set in field in 1975 now down only 3". Removed CIM and drove Telspar pipe with CIC down on iron set beneath CIM. Top of CIC down 2'. Nothing to tie to. Post with disc taken in 1975 has now fallen over.

#751204 (4)

¼ Cor. 12-13 Kalman, 107-15

8-15-83, 1/16E: Found pipe down 2" in old E-W road but top appears bent East. Reference tree SW now only stump. Reference tree SE OK. Purpose of survey was to stake section line to grade E-W road on South side of line. Both corner and reference trees could be destroyed in road grading.