8-26-1965 ~~set C I W over iron rod, stone pieces~~ #1
6-10-1976 Removed C.I.W. - Set 1¼" pipe (1' deep) on inter. of ¼ lines
¼ corner Center 21 Kalmar 10 7-15
5-1872 Hunter P 197 No 207 L 21. L. Simonson, F Richert
#752109
set stone 3 x 4 x 24 at inters lines.
N 89° 25' W
1/16 east set stake M & L 20.05 - farmers will set stone.
1/16 north set stone 4x6x20 M & L 19.90 N 28' E
1/16 center NE ¼ 21 set stone 4x8x16.

5-1876 Hunter P 296 No 291 L 21 J Murry, 2r Campbell.
found stone P 197.
— 1/16 south set stone M & L 19.95.
— 1/64 south of above 1/16 cor. set stone 3x4x18 M & L 9.97½.
over)

8-1965 J Kerr S 21 S Thompson.

dug extensively, good terrane for corner to stay stable but found a likely piece of limerock South east of corner lying flat near surface like it had been thrown from corner area. found marked depression of soil structure just east of corner of 3 way fence. accepted this as corner site.

- ~~set CI Moner 1/2 x 24" rod~~. removed CIM & 1/2" rod - set 1 1/4" pipe 6-10-1976

Corner lines well with all fences N-S-E.

- 1/16 north found old stone 13 1/2 from Cor 21 as set near 2' deep. just west of under N-S fence and 2' SW of treasoted pst

a small electric fence steel post up several inches as drawn just north of stone below

¼ Corner Center 21 Kalmar 107-15 #2
#752109

6-8-76 (1/16th E) Found stone 2" x 8" x 15" under the N-S fence. Set a ½" x 24" rod on the E side of the stone and tied ribbon on the fence. Corner falls 27½' N of large R.R. tie post set on W. side N-S. fence.

6-9-76 Dug 3'x3' SE of Kan's CIM. Found nothing. Mucky condition 2' deep.

6-10-76 Reset center at true intersecting lines after electronic measurement. Removed CIM and set 1¾" O.D. by 3' pipe .45' E and 1.32' S 12" deep. Set electric~~ian~~ fence post along side. Corner lines with fences far north and west.

R.P: Spike in corner post WNW 3.6ft
to fence N-W-S

6-8-76 Center of NE 1/4 : Dug 2'x3' on N. side
of corner post. Found nothing.