X ~~8-23-1968 set CIM over pipe in blacktop~~ 10/25/91 set 1" sq. pipe ①
~~11-8-93 found stone 10.6 east 7.4 south. reset CIM~~ #752506

1/4 Corner 25-26 Kalmar 107-15

Note: May 1975 Pat & T.F. report that corner is filled over in road regrading

5-1892 Hunter P 204 no 212 & 26 Hogans-Duffin.
found stone in center road.
-1/16 west set stake M & L. 19.81 (1307.5). to center 26.
a stake intersects lines.

Line from E 1/4. 26 to W 1/4 26 1309.5

1315.7 stone 1315.7 stone 1307.5 1307.5 Record.

found post set CIM. 1314.7 pipe. 1314.7 CIM. Cent 26. 2612.8 found nail tractor dug

8-1966 J Kerr

Hunted for corner. Meas south line 26 (over) dug 20' hole with backhoe found no stone may have destroyed stake. found nail driven in at about recorded chainage from center 26. set pipe. will set C/M when fill settles.

RP ::: in end galv culv. SW 30.25
" NW 22.6.

8-23-1968 set C/M tookadd RPs.
Disc south side power pole 22215 SE 55.7.
" west " " " brace 22216. SW 42.6
Center 14" maple in yard. NE 109.7.

Card # 2. 1/4 25-26 Kalmar 107-15 #752506 (2)
5-7-1973 research for correctness of corners.
5-1872 Hunter P 204 No 212. & 26 J Hogane, J Duffin.
" found stone set in center of road - did not run to "L"
-16 W "6" set stake marked 1/16 midway betw "5" and "H"
and drove it low. 19.81 (130 7.46 to center 26.
a stake set inters lines.

11-7-73 found true center 26 too deep to find in 8-23-68.
very near to where C/M was and reset with 1/4 x 5' pipe.
11-8-73 dug with backhoe in center inters roads. ground
frozen 6" found limestone 4 x 6 x 16 down 4 feet with piece of
crockery stone cracked but all pieces in place and ideally
centered stone 10.6 east - 7.1 south of Ker C/M.
pulled C/M and placed over stone and 1" pipe (over

removed pipe below old C.I.M also. R.P.S. stone and C.I.M. punch hole in south end 24" road culv.

punch hole in north end 24" road culv.

direc on S side PP# 22215

direc on W side PP# 22216

center 14" maple in middle yard.

	stone		C.I.M.
	33.45	SW	30.25
	35.32	NW	22.6
	43.18	SE	55.7
	44.55	SW	42.6
	105.0	NE	109.7

C.I.M. 12.65 direct mear NW by. of stone.

-note stake found 1.4 due north of 1/4 26-27. set C.I.M. 1.1' N.

11-27-73 elect. mear N to C.I.M at 1/4 23-24-25-26. 26.33.77

Mear S to C.I.M at -25-26-35-36 2600.86

Kalmar 1/4 corner 25-26 #752506 (3

Gov't Corner Karrick 1554

40.00 set ~~[illegible]~~ 1/4 sec. post in mound with trench, pits charred stake + Orange Orange Scribe Set 15cc

April, 1863 P.C. Compton Pg. 72 No. 103 shows 1/4 Cor. used to set Center 25 @ intersecting lines.

2-21-85, 1/4 Cor 25-26: Could get no dip at all. Road appears newly graded. Think CIM gone but could just be deep. Only one R.P. remaining — a pop cap in power pole SE'ly

6/16/86 FD 2 REMAINING SECTIONS OF CIM DOWN 3.2' REMOVED AND FD 3/4" PIPE STANDING GOOD 4' DEEP SET NEW CIM OVER PIPE AT RD SURFACE. CORNER 2' S. & E-W RD & 1' W & N-S RD

OVER

6/16/86 PPs TO CIM PUNCH MARK IN TOP N. END C.M.P. NW 42.64, PUNCH HOLE IN TOP N. END C.M.P. NE 50.13, CSD IN SW SIDE POWER POLE SE 43.35

10/25/91 County Surveyor set 1" sq pipe/cap in ℄ blacktop C.R #156 inline of ℄ twp rds N-S CHD RP iron SSE Now 165.15'