~~6-29-1964 set C/M one 1¼ x 16" pipe~~ ①
6-19-1970 found true corner ⅞ "130" bolt reset C/M one inch bolt.
¼ corner. 29-30 Kalmar 107-15.
#752906
5-1871 Perry. P162 no 185 L 29-30-31-32.
relocated corner M & L. 39.95 no desc (263607
1/16 south set stone 5x13x21. M & L. presumed 19.97½.
1/16 west set temp joint

10-1939 J Kerr. B16 P40 work done to grade E-W road.
set ⅞" x 30" bolt M & L 2631.0.
+ on top large red boulder. NW 46'

6-1964 J Karr. found 1/2" rod, bent (Not 7/8 x 30) set
replaced corner. set CIM over 1 1/4 x 16" pipe.

Dist	power pole	NE	53.0
"	fence post	N	58.8.
1"	pipe up 10" in fence line	N	100.0.

Corner lies 5.0' south center line traveled road.

6-18-70 Co Surv run & re meas N-S line as in B 16 P 40 10-1939. found that CIM above not set on true corner but on some accum corner. dug and found square head bolt as in B 16. - Meas now 2630 north to CIM, 2630.45 south to 1 1/4 iron pipe but found iron pipe now should go 1.36 each to line other 2 corners as before. Corner now in center road still in line fences about 1' east of N end of fence running N.

1/4 29-30 Kalmar. 107-15

6-18-1970

found 1/2" rod used to set C/M. 6-1964 in error.
dug for 7/8" x 30" bolt set 10-1939 M & L as set 1871.
found bolt down 3' in center road.

Disc in pp	NE	48.18.
" " fence post	N.	54.15
1" pipe under fence	N	94.75

which lies 1.56' west of deed line

#752906 (2)

Card # 2. 1/4 29-30 Kalmar 107-15

- pipe north under fence that was 100.0 Now. 94.75 and it lies 1.56' west of being in direct line with C/M north.
- Disc in power pole (was 53.0) Now. NE 48.18
- Disc in fence post badly pulled north. was 58.8 Now N 54.15. corner now 5.25 north and 1.46 east of old C/M
- bolt head found was 34" below road surface
- C/M now down 6" " " "

Good Water Kansas 1855

40.00 set 1/4 sec post - mound with branch, pits, charcoal stake & Orange Orange scrub NE - SW

11-6-82, 1/4 Cr 29-30: Found CIM leaning badly to East. Dug down to bolt beneath and reset CIM over it. Corner in line with main lines of fences North and South and 1½' So. & E-W road.

RP: CSD in pp NE 48.19 (Removed old disc which was very loose)

Punch hole Stop W. end CMP in driveway NNE 32.08

Punch hole top E. end CMP in driveway NE 46.02

Pipe under fence North North 94.75

8-6-98 55
MW EA BB

✓ 1/4 Cor 29-30 107-15 Kalmar

T52906 F fd CIM leaning badly in E-W Twp Rd dug out in Pieces down to 7/8" bolt set in 1939 Set CIC/6' long Telspar pipe at 7/8" bolt location The Corner Fell in @ E-W Twp Rd and in line of Main Fence line North