7-2-1974 Set a R.R. spike as a final corner in C.R. # 39

#753604 (1)

1/4 corner south 1/4 36 Kalmar 10 7-15
North 1/4 1 Salem 10 6-15

2-1882 Hunter P375 No 366 L1 Hinds Bros.
Corner gone, but Mr Hinds avers a large cedar post was set on line and 2 rods south of org corner.
- Meas east 39.97. or.
23.31½ to prop. corner thence 16.65½. = 1099.23 = 1539.19

4-1902 Armstrong P34B L1 John Manahan.
found org stake in line of fence south.
- Meas east to engraved corner 40.04.

Hunters R R Notes. 2244' north to ℄ R R tracks. (over)

7-2-1974 Book 49 P. 33

Reset the's corner using J. Kerrs 2636.0 meas. from the E. since when he meas. there was a cross fence here (North- or South) and used the ℄ of the road for N-S control.

Put a R.R. spike in as the cor. + took R.P.s

Rivet in top. center east end 18" field drive C.M.P. N.W. 61.21

C.S.Disc + spike W. side 18" chinese elm. South 51.93

Govt Notes, Karrick 1854

40.00 S.E. post + stone a 5" chisel slash to quarter section post. Built mound with trench

Planted S.E. Osage Orange seeds. N.E. angle

Seeds. 6/4/92 County Surveyor FD RR spike in ℄ of CR 34 in good cond.

(Set ½" REF RDS) RPs 2.0' south to E-W fence

2.0' east to west gate post.

1/4 CORNER S 36 KALMAR 107-15 (2)
N 1 SALEM 106-15
#753604

6/4/92 Cont.
A @ REF ROD
∠ RT S1/4 36 TO REO LIGHT ON KROC RADIO TOWER
43° 31' 49.5"
To S1/4 36
VA 90 24 59 dvol
SD 92.625 HD 92.62

6-28-93, Turned out June 1992 Ref ∠ of 43°31'49.5" for
92.62' (Set P.K. Nail)

7-12-93, Set 5/8" Rerod w/cap as Corner in
℄ CR # 34 at PK location set from Ref on
6-28-93
R.P.'s
Mn/Dot R/w Mon. South 50.05'