4-6-77 CIM over stake + stone "Corner of Corn"

#1

#840904

1/4 corner 9-16 Oroville 108-14.

no records of any type or any knowledge or evidence, even farm fences have no rhyme or reason. See over

- 5-27-1969 J Kerr run section line from old record established corners - total mile 5260.7

Corner came about 2' from South edge traveled road

" " 1' east of directly over 30" galv culvert.

" " 53 ~~65~~ ± west of farm boundry fence running south which is near opposite rather poor farm line fence north.

- set only 1/2" x 11" rod which hit culvert edge in roadbed did not wish to create tension in land owners

-over-

set corner only To comply with manual laws.

in south end 30" culv 1' west of south 4.5'

in north end " " near north 21.35'

Hole in power pole # 37899 SW 47.2'

impossible To even imagine searching for orig corner lands low & grade deep from rock cut in slope east.

---

1916 Power Dam Survey - See Sheet #3060
plat shows "Stone" inplace - Meas. East 2582.1
West 2684.7
5266.8

Meas. South To protracted Cor 2642.6

1/4 Corner 9-16 Oronoco 108-14 #2
"Correction of Corner"
#840904

4-6-77 Dug with backhoe for stone recorded by Power Dam Survey. Dug from 2' East of fence South West for 7'. Found a stake 9' deep with stone on the East and West side and a stone over it. Drove 4½' pipe in the stake hole. Set a CIM at the road surface. Corner approx 50.5' E. and 4' North of Keris sion (removed) Corner 3½' S of ℄, 4' West of fence S, and 7' West of fence N. Dug through 2½' of post. Dug 2' [ ] 4' centered 4' No of a straight line between the section corners

R.P.'s Pop Cap S. side pp # 37899 SW 93.17
∴ top So end C.M.P. WSW 52 49
∴ top N end C.M.P WNW 53.82

Govt Notes M. Kavanagh 1854
40.00 set temp 1/4 sect. post
W+St on true line between sections
9 + 16 W 8.55'
40.00 set 1/4 section post ... mound
with trench pits charcoal stake
and Osage Orange stakes N.E + S.W