/ 10-1-71. set bedrail up 14" in place drag tooth etc

1/4 corner 10 – 11 New Haven 108-15 (1)
#85110L

12-1894 W Fraser P556 No 573 S 10, 11, 14, 15 alder campbell ackerman, etal
Could not find any corner or evidence or knowledge. – set temp point N & L
39.90 (2633.4'
– 16 south set long limestone N & L 19.95 (1316.7'
– 64 south set stake N & L 9.97½ (658.35'
between above 1/16 corner and temp stake at 1/4 10-11

1-1897 W Fraser P604 No 594 S 11 Fred ackerman
relocated corner as in P556 To set Center 11
no disc A corner set N & L 39.90 (2633.4

10-1-71 Co surv. found recorded 1/16 stone & iron bar between 1/4 10-11 and 10-11-14-15 5/16 stone a L-stone. 4x5x8" remaining. 4 long L-stone and 1¼"x24" solid pointed rod - set iron near surface as 1/16 corner. RP 1/16: 243.8 ESE to ø: ø with punt as center S end 3' wlv.
46.2 8.5' W & N to Coke cap W side of cor post fe N.
5.0' S to barb wire fence with edge traveled road.
N½ = 1317.34 elec (1974) S½ 1317.50 elec. 1974
— re-run line found 1/16 corner at 1317.65 R 1316.7
proj. line north and doubled meas. land in fence row
dilated -3' dup - found drag tooth badly tilted down
30" 4' north of E-W fence. point of drag tooth within
a few tenths of line & meas so set bed rail on
exact proj. line and 1317.65 Ref. references set long
bed rail at corner upht

1/4 Cor 10-11 New Haven Twp 108-15 (2)
#851106

6-12-1854 Govt Notes John Aushing, Dep. Surveyor.
North between sections 10 and 11.
40.00 chs. Set 1/4 sec. post, raised mound with trench as per instructions and drove charred stake.

12-31-1980 1/4 Cr 10-11 : Found bed rail badly bent over. ~~Corner~~ Ground being froze so could not remove.

1-6-81 Jack hammered out bent portion of bed rail to find remainder standing straight. Broke off top bent part. Drove a piece of tetspan down on the corner but did not have a cap. Set a survey marker sign and pert 1.8 East.

Unit Notes

40.00 Set a quarter section post in mound of rock & soil, deposited charcoal, much trash & pottery.

Planed Orange Orange and E & W.