Certificate of Location of Government Corner

ID#: 440307 **Description:** N SEC COR 3 4 44 **Date Set:** 9/21/2007 **County:** Olmsted

Section: 03 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 4 1/2' north of centerline of CSAH 6 and 23 1/2' east of centerline of field entrance south
County Survey Disk in NW side PP SW 75.18'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes No Dep. Sur. Noted 79.50 chs. Intersected 1st Standard Parallel line 330 lks. West of quarter section post south of section 33. Deposited charcoal and raised mound of earth and sod and cut trench and planted osage orange seeds east and west between pits and trench.

9-1853 Gov't Notes on S 1/4 corner of Sec. 33 to Township 105 North of Range 14 West. West on south boundary of section 33. 40.00 chs. Set quarter section post. Made mound with trench and drove charred stake in center and planted apple tree seed in NW corner. Thomas Hunter explains above incorrect Gov't chainage between N Sec. Corner 3-4 and S 1/4 corner Sec. 33 in Survey No. 341 P. 348.

5-10-1878 Thomas Hunter (P. 343 No. 337), County Surveyor, set a stone 4"x8"x24" at 81.15 chs. From NW corner Sec. 4. Corner fell on the edge of embankment on the north side of traveled track on line between S Sec. Corner 32-33 and S Sec. Corner 33-34.

4-23-1906 Charles Armstrong, County Surveyor (Book B, Page 104) has stone marked on plat.

8-25-1931 County Highway Department Pg.5 BK.61; Found 15" cedar stake over stone 18" under surface. Stone falls 6.1' north & 1' west of PI.

4-6-1941 A. Armstrong(Book 112 P.75) found 2 survey stake risers and set 3/4" rod riser.

12-17-1945 County Highway Department (Book 166, Page 1) shows ties for PI at north corner Sections 3-4 104-14

5-1953 McGhie; Stake & stone with 3/4" steel rod riser. RPs-spike in PP #11047 NE 122.7', spike in TP SE 57.15', spike top concrete corner fence post S 34.15'.

8-2-1974 County Surveyor dug with backhoe and found the recorded stone. Set a CIM flush with bit. Mat in CR 6.

11-06-2001 County survey crew found CIM down 0.7' in good condition.

9-30-2005 County survey crew found CIM down 0.7' in good condition.

7-25-2006 County survey crew found CIM down 0.7' in good condition. Tied out corner for 2006 road construction.

8-23-2006 County survey crew removed CIM for road construction. Found stone down 3' in good condition.

9-21-2007 County survey crew set 1" square pipe w/cap at surface from 2006 construction tie out.

1-29-2013 County Surveyor computed a new corner location on the standard parallel by intersecting the west line of Section 3-104-14 with the south line of Section 33-105-14. The computed position is 0.10' south of the inplace monument.