Certificate of Location of Government Corner

ID#: 440308 **Description:** N 1/4 SEC COR 3 44 **Date Set:** 10/6/2005 **County:** Olmsted

Section: 03 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 6 and 170 1/2' west of west edge of concrete of BR. #55573
This corner is located by GPS measurement

Corner History:

No Gov't corner set.

4-29-1875 Thomas Hunter (P. 271 No. 269), County Surveyor, set a stake midway on the North line of Sec. 3 and on line of the S. Sec. 33-34 and N.W. corner Sec. 3.

5-14-1878 T. Hunter, unrecorded No.337 (Field Book 5, Page 67) No corner ever set. Reset by SE corner 33.

8-25-1931 County Highway Department (Book 61, Page 3) Assumed corner PI Sta 28+35 Set 80d spike.

11-2-1940 County Highway Department (Book 112, Page 6) Assumed corner PI Sta 108+22.6 Set hub over old spike.

12-17-1945 County Highway Department (Book 166 P. 2) had 3/4" iron with hub and tack as corner. P.O.T. Sta 108+22.6

8-8-1974 County Surveyor set a C.I.M. midway on the north line of Sec. 3 and on line of the S. Sec. Cor. 33-34 and N.W. Cor. Sec. 3. Corner is 404.14' west of the S. Sec. Cor. 33-34. C.I.M. is over an iron rod in Co. Rd. 6. Did not dig at this corner as it falls in such a deep fill we couldn't dig deep enough with the backhoe and records of T. Hunter call for a stake in 1875. No references taken.

11-06-2001 County survey found CIM down 0.3' in good condition.

9-1-2004 County survey crew found CIM without head down 0.7' in good condition. Tied out corner for road and bridge construction.

10-6-2005 County survey crew set 1" square pipe w/cap at surface from 2004 tie out.

1-29-2013 County Surveyor computed a new corner location on the standard parallel by intersecting the n-s quarter line of Section 3 with the south line of Section 33-105-14. The computed position is 0.08' south of the inplace monument.