Certificate of Location of Government Corner

ID#: 440408 **Description:** N 1/4 SEC COR 4 44 **Date Set:** 9/21/2007 **County:** Olmsted

Section: 04 **Township:** 104N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 2' south of centerline of CSAH 6 and 42 1/2' west of centerline of west Sportsmans Club driveway north
County Survey Disk in E side PP NNW 61.26'
20d in W side 10" B. Oak SSE 64.1'
This corner is located by GPS measurement

Corner History:

5-10-1878 Thomas Hunter (P. 343 No. 337), County Surveyor, established corner midway and on line on north line of Section 4. Set stone 6"x12"x25" in center of road.

4-23-1906 Charles Armstrong (P. 104 Book B), County Surveyor, found recorded stone as corner.

11-1927 J. Kerr (Book 3, Page 30) Found corner to be 31' north of concrete post and on line.

8-25-1931 County Highway Department (Book 61, page 6) Found stone. Stone falls 0.3' north of present PI.

10-22-1940 County Highway Department Bk.112 Pg.4; Hub over stone monument 3/4" rod riser. Found stone 3' north of PI. RPs- hub 4' north of SW leg of windmill ENE 98.85', hub east side of fence S 74.7'.

12-17-1945 County Highway Department (Bk.166, Page 1) Stone riser 3/4". RP still in place- NW corner of conc. Fence post south 33.2'.

5-1953 K. McGhie, Land Surveyor, found stone and set 3/4" iron riser. Co.H.D. (Book 112 P.4) had hub over stone monument with 3/4" rod riser.

7-27-1974 County Surveyor dug with backhoe and found hub, rod, and stone 3' deep in centerline of Co. Rd. 6. Accepted corner and drove a 3/4"x3' rod on the south side of the stone and set a C.I.M. over all.

11-06-2001 County Surveyor found CIM down 0.5' in good condition.

9-29-2005 County Surveyor found CIM down 0.6' in good condition.

7-26-2006 County Surveyor found CIM down 0.6' in good condition. Tied out corner for 2006 road construction.

8-23-2006 County Surveyor removed CIM for road construction and found stone down 2.6' in good condition.

9-21-2007 County Surveyor set 1" square pipe w/cap at surface from 2006 construction tie out.

1-28-2013 County Surveyor computed a new corner location on the standard parallel by intersecting the N-S quarter line of Section 4-104-14 with the south line of Section 32-105-14. The computed position is 0.16' north of the inplace monument.