Certificate of Location of Government Corner

ID#:450206 **Description:** 1/4 SEC COR 2 3 45 **Date Set:** 3/29/2005 **County:** Olmsted

Section: 02 **Township:** 104N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of twp road south and 1/2' south of centerline of CSAH 6
County Survey Disk in NW side PP SW 62.02'
County Survey Disk in NE side PP SE 64.58'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Ball,north on true line between sections 2 & 3; 40.0 set 1/4 section post in mound of earth and sod with trench and drove charred stake in center of mound and planted osage orange seed in SE corner.
Gov't Notes, John Quigley, Deputy Surveyor, North on true line between sections 2 & 3; 40.0 chs set 1/4 section post and built mound with trench per instructions. Drove charred stake in center and planted osage orange seed in SW corner.

6-21-1877 T. Hunter Pg.319 No.313; Found no corner, set stake on line.

6-23-1877 T.Hunter Pg.320 no.314; Found and used corner. 16 east set stake, 16 south set stake.

6-1895 W.Fraser Pg.637 No.574; Couldn't find stake. Rerun line and set boulder stone as corner and tested corner and line fell on stone set. 16 east set iron, 16 south set stake & boulder, 16 center SEW 1/4 2 set iron stake.

1940 county highway department found iron pump handle Pg.637 at 1/16 corner east. RPs- 1/2' rod over hub, 1 1/2" pipe N 33.05', 16 east 3/4: reinf bar; RPs- 1 1/2" pipe S 33.0', 1 1/2" pipe N 33.05'. Bk.109 Pg.76 says all above data on 1/16 corner east reset 1/4 2-3 by reproducing meas & line from center 2 over pump handle 1319.75'. RPs tp 1/4 2-3- hub in pasture WNW 100.0', hub in fence line N 66.84'.

6-1-1979 County Surveyor doubled line and measure from the stone found at the center 2 over the pump handle found at the 1/16 west. The point came just .3' west and .19' north of the county highway department 1/2" rod in place. Dug and found nothing.

6-12-1979 County Surveyor doubled line and measure from south section corner 2-3 over the 1/16 north. The point came further south than we had dug before, so we dug again and found a 11"x7" topped boulder over 2 1/2' long with a stake on its side. Set a 1" pipe w/elbow on the east side of the stone and a 1/2" pipe in the stake hole. Set CIM at the road surface over the stone. Corner is .75' east and 2.5' south of the county highway department iron(removed). RPs- CSD NW side PP #12976 SW 43.03', punch hole top W end CMP SW 29.47', punch hole top E end CMP SE 28.45'.

6-19-2000 County Surveyor found CIM down 0.5' in good condition.

5-14-2003 County Surveyor removed CIM, found 1/2 iron rod down 2.2', referenced location for road regrade.

3-29-2005 County Surveyor set 1" square pipe w/cap at surface from computed angle because B.S. was disturbed (pt. Wendt). CSD with concrete nail in NW side of PP (no #) SW 62.02', CSD with concrete nail in NE side of PP (no #) SE 64.58'. Monument falls 0.5' south of centerline of CR 6 and falls in centerline of twp road south.

4-29-2009 County Surveyor found 1" square pipe at surface in good condition.