Certificate of Location of Government Corner

ID#:511604 **Description:** 1/4 SEC COR 16 21 51 **Date Set:** 7/8/1976 **County:** Olmsted

Section: 16 **Township:** 105N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 2 1/2' south of centerline of E-W twp road and 5' east of fence north
County highway disk in SE side PP #2283 NE 33.03'
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes William A. Jones, Deputy Surveyor West on true line between sections 16 and 21. 40.075 chs. Set a quarter section post. Burr Oak 5 in. N59ºE 245 lks. Dug trench as per instructions. 80.15 chs. To Section Corner.

4-25-1878 Thomas Hunter (P. 338 No. 332), County Surveyor, found a stone in the center of the road.

11-5-1968 John Kerr (B.101 P.28), County Surveyor, dug for the corner. Found a mark in clay and accepted it as the spot where the stone has stood. Set a C.I.M. over 11/4"x18" pipe as the corner.

7-8-1976 County Surveyor dug with the backhoe East of Kerr's C.I.M. after finding Sec. Cor. 15-16-21-22. Found a 2"x10"/11"x18" limestone (broken) 2' deep 4.5' East and 4.6' South of Kerr's C.I.M. (removed). Found stake remains on the North side of stone. Drove an iron in the stake hole and placed the stone along side. Set a C.I.M. over the iron.

CORRECTION OF CORNER: THE CORRECT CORNER IS 4.5' EAST AND 4.6' SOUTH OF KERR'S C.I.M. (REMOVED)

6-11-1982 County Surveyor visited corner site, road being regraded starting 300' east and going east. The 3 ties are sufficient at the present time. Took 3 pictures from E-N-S.

11-9-2006 County Surveyor found CIM down 0.6' in good condition. Maple tree is now down and angle iron corner post replaced. Fence to the north ok, fence to the south gone through pasture but does continue along field.