Certificate of Location of Government Corner

ID#:530106 **Description:** 1/4 SEC COR 1 2 53 **Date Set:** 8/1/2007 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 19 and 14' south of centerline of twp road west
County Survey Disk in NE side PP NW 87.44'
1/2" rod E 99.89'
60d nail in leaning CP E 60.45'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: McKarrick; North random 1 & 2. 40.0 set a temporary 1/4 section post east on true line between section 1 & 2. 39.57 set section post. RPs- 8" burr oak S60 W 94 links, 12 " burr oak N 65 E 182 links.

7-1876 T. Hunter Pg.301 No.296; Corner gone, road graded "down" several feet and took line Of fence running west claimed to be set from original corner as line to set center section 1.

6-1903 C. Armstrong, Pg.63p; Evidently found or set no corner according to plat, used corner post of fence running wast as pilot to set line north.

8-1940 J. Jerr B.20 Pg.62-65; Set 1"x3' pipe on line between section corners. (Used 2" shaft set by county wrong corner). Measured south 2619.62, north 2591.21, and measured west to center 2 2640.58. RPs- Cross in north end culvert NW 44.42, cross in south end culvert W 34.4 (1968).

7-1968 J. Kerr Set 1/2" rod on random north of telephone pole to hold line. Telephone pole south 26.6, center field drive south east 35± rod lies 5'± south center road E & W about 4' from south edge. Meas. West to center 2 2640.2. 1/16 north set rod on section line 1280.96.

6-20-1969 J. Kerr reset corner with 1/2" rod until road has all its rock lifts. Found rod 100' east and everything else gone. Reset in line rod set at 1/16 area west. Set new ties; punched single punch on top clamp holding flare and of culvert in place, south end 18" road culvert running under road west, SW 50.16. Same on north end NW 57.75. Head of nail (60D) driven clear in on east side power pole #16310 up 18" NW 83.53. 16 north found rod placed 7-1968 as 1/16 corner, proved only way to set section corner north. RPs to 1/16 rod- Punch mark in top culv. End clamp very near east 37.87, pine tree symbol disc on pp#16306 (moved in grading). 1/16 rod at 647.6 south of NW corner 1 in centerline road. RP- 90.08 NNE to seam in east end conc. Culvert apron. Property corner 50'east, RP- 86.05 to seam joint.

9-15-2003 County Surveyor found 1/2" iron rod down 0.9' in good condition.

9-16-2003 County Surveyor set 1" square pipe with cap over 1/2" iron rod at surface from local ties.

4-13-2007 WHKS & Co. found and used monument.

5-2-2007 County Surveyor found 1" square pipe w/busted cap at surface in good condition. Replaced cap.

5-25-2007 County Surveyor removed 1" square pipe w/cap at surface for 2007 overlay.

8-1-2007 County Surveyor set 1" square pipe w/cap at surface from 2007 overlay tie out. Tie matched to PP, did not look for 1/2" iron rod & 60d nail in leaning CP E 60.45'