Certificate of Location of Government Corner

ID#:530605 **Description:** W SEC COR 6 7 53 **Date Set:** 2/11/2005 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7 1/2' west of centerline of waterway and 209' west of centerline of CSAH 20
Post w/sign 1 1/2' west
This corner is located by GPS reference stations "SW A & B"

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor North between sections 7 and 12. 80.00 chs. Set post and drove charred stake. Built mound with trench and planted Osage orange S.E. and apple seed N.E.

6-1892 William Fraser (P. 502 No. 472), County Surveyor, states the corner was in a slough and gone. Set a stake as the corner on the line from the W. 1/4 Cor. 7 to the N.W. Cor. Sec. 6 and at 1/3 the distance. Set a stone at the W. 1/4 Cor. 6 midway and on line and set a stone at 1/4 Cor. 6-7 at the intersection of the line from W. Sec. Cor. 6-7 to Sec. Cor. 5-6-7-8 and the line from the S. 1/4 Cor. 7 over the center of Section 7.

11-1907 Charles Armstrong (P. 110B) found a red cedar stake.

10-17-62 county highway department found red cedar stake with nail in top (in field). 1/16 North county highway department cone block with x cut in tip. R.P's: spike & disc in 15" pine SW 24.8'. Spike & disc in P.P. NW 55.5'. Spike & disc in 12" pine SE 43.5' tack in corner post NE 57.1' (BK 175)

7-1964 John Kerr, County Surveyor, could not find the corner. Set a 7' rod (up 1') as the corner on the line and at double the measure from the N.W. Cor. Sec. 6 over the W. 1/4 Cor. 6.

3-13-1973 Found 3/4" pipe down 8" ± North comes in old road area just North of park type area of church. RR spike on NW side guge pine SW 24.8 Co. tie. RR spike on SW side scarred up power pole # 9321 on West side road as it curves SW by NW 79.23.

8-3-1977 The County Surveyor found the corner had been destroyed by the construction of a new drainage ditch. Set a Cast Iron Cap on a 4' long square pipe as the corner at the intersection of the line from the N.W. Cor. Sec. 6 over the W. 1/4 Cor. Sec. 6 and the line from Sec. Cor. 5-6-7-8 over the S. 1/4 Cor. 6.

8-29-1984 County Surveyor corner destroyed by cat building new drainage ditch and cat still working so did not try to replace.

10-8-2003 County Surveyor set 2 points to GPS to determine location and reset corner.

2-11-2005 County Surveyor set 4' telspar pipe w/cast iron cap down 0.3' from GPS and traverse data. Set post w/sign.

6-5-2007 County Surveyor found cast iron cap on telspar pipe up 0.1' in good condition.