Certificate of Location of Government Corner

ID#:530606 **Description:** W 1/4 SEC COR 6 53 **Date Set:** 7/24/1964 **County:** Olmsted

Section: 06 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 4' east of centerline of N-S twp road, 12 1/2' north of centerline of residential driveway NE and 64' north of fence east
Center of Twin Burr Oak NE 78.0'
120d spike in S side of most southerly 16" Pine NW 38.96'
County Survey Disk in PP NE 29.42'
This corner is located by GPS measurement

Corner History:

SGov't Notes 40.00 set quarter section post. Bur Oak 11 S 13° W27 links. Bur Oak 8 S 50° E 64 links.

6-1892 W. Fraser (P502 No 472). Corner gone set quarry stone M & L 39.865 (2631.09). North set stakes 8.75 (577.5') then 21.305 (1406.13) then 9.81 (647.46) to twp corner. Meas South 39.865 (2631.09). East set stake 9 chs. (594') in line center 6.

11-1907 C. Armstrong (P.110 B) found limestone took bearing trees. 1/16 South set stake M & L 19.96 (1317.36)

5-1917 Chas. Armstrong Book K page 19. plat shows stone with meas South of M & L 19,96 1317.36.

9-1941 J. Kerr (B26 P.4) ran from twp corner South found limestone with stake on West side P502A P110B at 2634.8 as W 1/4 6 105-13. Also found red cedar stake at 5269.0 as W 6-7 105-13. R.P.'s W 1/4 6 center fork of twin br oak NE 78.0. twin br oak SE 39.0. Elm E 131.5. Br Oak WSW 40.2. Using all 3 corners as found, W 1/4 6 lies .4' East of direct line 2634.8 North 2634.2 South .3' South of midway.

1946 County Highway Department (B175 P.9) found 3/4" pipe. R.P.'s: Sp Oak stump SE 39.8. Sp Oak stump WSW 40.33. Sp Pine stump NW 46.2.

1962 J. Kerr, Spk & disc in 15" elm E 35.1'. Spk & disc in twin oak SE 38.8'. Spk & disc in 12" oak W 40.4'. Spk & disc in 2nd pine North of oak NW 44.2'

7-24-1964 J. Kerr found pipe, glass etc. above the stone. Set C.I.M. over 1 1/2" x 10" pipe. 120d South side most Southerly pine NW 38.96. Center large elm E 34.5. Center twin Bur Oak NE 78.0. Center large Elm E 131.5. Line farmyard fence running East S 64.0. Section corners N & S 2634.8 1/4 Cor. On line.

3-13-1973 County Surveyor at 1/16th South found 3/4" pipe down 10" ± no conc block. RR spike on NW side 28" pine 24.8 or very near (brush). RR spike on SW side chewed up power pole #9321 NW 79.23. No sign of line run by J. Kerr in 7-1964

6-15-1988 County Surveyor found CIM in good condition in gravel road.

9-15-2006 County Surveyor found CIM down 1' in good condition.

5-2-2007 County Surveyor found CIM down 1' in good condition.