Certificate of Location of Government Corner

ID#:531106 **Description:** 1/4 SEC COR 10 11 53 **Date Set:** 4/29/2009 **County:** Olmsted

Section: 11 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 27' NE of centerline of CR 116 on curve
County Survey Disk in S side PP #51448 WSW 51.16'
County Survey Disk in SW side brace pole #44798 SE 6.42'
Sign on brace pole 6 1/2' SE
This corner is located by GPS reference stations "Struthers and 1/16th South"

Corner History:

1854 Gov't Notes M.G. Karrick 40.00 set 1/4 section post White Oak 15 W 56 E 55. White Oak 17 S 36 W 58.

1-1858 T. Hunter (P46 No.68) used corner West 39.74 (2622.84) S89W South 19.85 (1310.1) M & L N10W.

7-1923 J. Kerr (P402B) found 1/16 corner stake remains set by Hunter (P46) and his B tree set stone and stake over remains of old stake. Meas West to Chas. Armstrong stone in center SE 1/4 10 1282.5.

8-1940 J. Kerr (B20 P.62-65) run line from NW corner 2 to SW cor 11 did not set above corner but meas line between 10-11 5242.75 2-3 5208.76 SW corner 11 found stone 2 x 4 x 18 packed in stone.

5-1921 Chas. Armstrong (Book B page 53) plat shows stone at 1/4 corner. Meas West 29.80 (1966.8) then 9.96 (657.36) to center 10. Meas South 19.85 M & L 1310.10 to section corner. Center SE 1/4 10 N14E 61 lks 40.26. 1/16 corner N61W 56 lks 36.96. Meas from above 1/16 East to 1/16 on E side SE 1/4 10 19.93 1315.38.

5-10-1973 County Surveyor found 1/16 stone South set by J. Kerr 7-1923 4' deep in center N-S road near line N edge road East and 1.0' South of old fence running West to stone J. Kerr found in 1923 at center SE 1/4 10 set by Armstrong (see card #2 for RPs to 1/16 corner).

5-11-1973 County Surveyor project line North over 1/16 pipe over stone doubling distance of 1310.22, dug entire area found nothing. Set 5/8" x 2' rod as temp corner. 26.3 E to staple on W side TP up 4' facing corner. 81.65 SW to punch mark in center 1" dia knot up 2' on SE side PP #13314.

12-16-2003 GGG Inc. found and used 5/8" iron in survey of NW 1/4 section 11.

4-29-2009 County Surveyor found 5/8" rerod down 0.5' in good condition. Accepted 5/8" rerod location as final and removed. Set 5 1/2' telspar pipe w/Cast Iron Casp at surface at rerod position.