Certificate of Location of Government Corner

ID#:531406 **Description:** 1/4 SEC COR 14 15 53 **Date Set:** 7/29/2011 **County:** Olmsted

Section: 14 **Township:** 105N **Range:** 13W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is down 1.5' in cultivated field
This corner is located by GPS reference stations "Nicklay A & B"

Corner History:

Gov't Notes 40.00 set 1/4 section post. White Oak 7 S 45 W 43. Aspen 10 N 44 E 49.

1-1894 W. Fraser (P.543 No.504 S.15) John Clard estate. could not find corner set White Oak stake from properly marked SW BT still standing. Came in center old road. Meas North 9.93 3/4 (655.87) to while Oak stake then 9.93 (655.87 to 1/16 cor. an iron stake then 19.87 1/2 (1311.75) to section corner. Stake and stone found S 1/4° E. Meas West 9.98 1/2 (659.0) to stake then 9.98 1/2 to 1/16 stake then 9.98 1/2 (659.0) to stake then 4.99 1/4 (329.5) to stake then 4.99 1/4 to center section. A 2 x 8 x 24 stone set this survey. Meas South 9.94 (656.04) to stake then 9.94 to 1/16 stake then 9.94 to stake then 9.94 to sec. cor. a 2 x 12 x 26 stone 1' East old cor post.

5-18-1972 County Surveyor meas and ran line from CIM at 10-11-14-15. Set small bolt at 1311.75, cont S to 2611.75 searched at 2623.5 found some charcoal.

2-13-1973 County Surveyor, 1/16 N found small bolt .86 East (nail) and found it to be 1312.21. Reset 1/16 with 60d nail .86 E .46 N of bolt still subject to meas under more favorable conditions. Set 1/2" x 2' rod on this line at 2623.5 and 2636.04 from center 15. Moving point from North West .07' making 1/16 nail off a little which will be properly reset offset 35' South at nail at 1/4 2623.5 and at center 15 stone and projected line West on this line cutting all trees the bothered line (some 8" dia). This line fell 21.15' South of rod set as 1/4 15-16 4-17-72 which was set on line from woodlot corner 673.22 R 671.55 North to 1/16 stone. Final 1/4 15-16 about 646.8 South of woodlot corner R 645.15. If line from East holds as true line ran by W. Fraser in 1-1894 something is sure wrong with 1/4 15-16 as set and at least 2 of 3 stones found North of it a problem.

2-14-1973 County Surveyor, 1/4 14-15 found traverse point by Nacklay driveway 2' N of fence E on line mailbox post and East edge road South, also positive RP's in traverse data. Re shot angles and distances from this point to center 15 (center witness red) and 1/2" rod reset as 1/4 14-15. Re shot line North directly to 10-11-14-15 found 60d nail at 1/16 cor. exactly on reset nail with 1/2" x 2' rod and referenced RP 1/16 North. 54.10 WSW to bottle cap and old disc on N side PP #13190. 26.95 due E to long conc nail then bottle cap on top of large oak corner post of new fence running East. Final on this 1/16 M & L 1311.75 as recorded by WR elec meas. Reset 1/4 14-15 with 1/2" x 2' rod at 2623.5 no reference poles or trees. Corner 3.66 E of lower wire of woven wire and 5.25 SE of steel corner post rag on fence.

2-2-1981 Dave Knutson and Jerry Schwarz report that 1/2" rod is plowed out they reset long spike from ties.

10-8-2003 County Surveyor did not find spike. Believe it to be destroyed when field was terraced.

11-2003 County Surveyor computed a coordinate position on the projection of a line from the northwest corner of Section 14-105-13 through the 1/16 corner south of said northwest corner and using the 1973 distance of 2623.50 feet from said northwest corner of Section 14-105-13.

7-29-2011 County survey crew set 4' telspar pipe with cast iron cap using the 2003 computed coordinates.