Certificate of Location of Government Corner

ID#:531506 **Description:** 1/4 SEC COR 15 16 53 **Date Set:** 4/26/1973 **County:** Olmsted

Section: 15 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 40' out into golf course
20d spike in NW side 6" Ironwood ENE 49.7'
30d spike in NW side 18" Elm NNE 48.55'
16d spike in old stump E 57.45'
Post w/sign 30' east
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick, Deputy Surveyor North between sections 15 and 16. 40.00 Set a quarter section post. Elm 11 in. S35°W 130 lks. White Oak 8 in. S27°E 18 lks.

6-1886 Thomas Hunter (P.410 No.399), County Surveyor, states corner and bearing trees gone. Set a stone midway and on line.

11-1886 T. Hunter (P.417 No.406) found stone.

1-1892 William Fraser (P.543 No.504), County Surveyor, found stone.

1-1894 W. Fraser (P543 No.504) est. found stone (P410).

4-1895 William Fraser (P.565 No.518) found a stone.

11-1939 John Kerr (P.544 Book B), County Surveyor, found boulder stone.

1941 Set ? Equal distance between section corners. RPs- 22.3' E of S box culv. Wing, 26.7' SE of N box culv. Wing.

4-17-1972 County Surveyor after running line from North set 1/2" x 3' rod as corner until proven otherwise (by roving or disproving NE 16 by line running East). RP's NNE to 16d W side 6" iron wood in cut off fence. 48.28 NNNE to 16d W side wired up 14" elm in fence. 57.37 ENE to 16d S side knarly elm in clump of elms. Corner seems to line with large trees running N 100' or so N. No fence East.

2-22-1973 County Surveyor reset corner again with 5/8"x2' rod. RPs- 48.28 NE to nail NW side 14" elm in fence, 57.37 E to 16D nail on S side Sly of clumps of elms.

4-26-1973 County Surveyor, corner destroyed in golf course construction. Reset a CIM over a 1"x3' pipe at the intersection of the section line between sections 15 and 16 and the east-west 1/4 line of section 15.

5-1983 M.Patterson & T. Ferguson; Retied corner. RPs- 20D on NW side 6" ironwood ENE 49.7, 30D on NW side 18" elm NNE 48.55, 16D in old stump E 57.45, CIM lies 40' out in golf course.

11-25-2002 County Surveyor found CIM in good condition down 0.2'. Set sign & post.