# Certificate of Location of Government Corner

**ID#:**531606 **Description:** 1/4 SEC COR 16 17 53 **Date Set:** 4/20/1984 **County:** Olmsted

**Section:** 16 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls 10' NE of stub fence and just NE of small NW-SE running ditch
County highway disk in 10" Elm SE 18.22'
This corner is located by GPS reference stations "Black Eye A & B"

**Corner History:**

Gov't Notes M.G. Karrick 40.00 set 1/4 section post. Elm 16 S 88 W 10. iron wood 7 S 17 E 170.

5-1856 Thos. Hunter shows 1/4 post 1/16 North 20.06 chs. M & L. 1/16 West 20.63 chs. M & L to center section small tract on SE 1/4 sec. 17.

11-1886 T. Hunter (P417 No.406) found old stake properly standing. Tested it by NW BT standing and found it correct, left stake in ground.

4-1895 W. Fraser (P.565 No.518) found stake as given in P.417 also B trees. Meas S to property stake 25.07 1/2 1654.95 then S to property stake 5.01 1/2 331.0 then S to section corner stake set 10.03 662.0. Bearing South S10W, North S1/2W. 40.12 2647.92.

11-24-1939 J. Kerr found Boulder on top of Stake 6' NW of Fence Corner and left as found. Reset corner with sq burr oak stake and set boulder stone on top. RPs- About 6' Nwly of fence corner, 68.9' S81°15'W to center 28" elm tree, 36.6' N16°30' W to center 12" elm tree.

11-28-1939 J.Kerr Pg.546 B; started from 1/4 16-17 as set. Ran S6°45' E to corner or 2574.04 corrected.

1962 County Highway Department used boulder ? 68.64 enter bottom 35.00. Original Gov't Notes 16" elm S88W 104 chs Root River 75 chs wide 46.18 9" ironwood S 17E 120 lks 79.2

4-24-1972 County Surveyor found no stone but drag tooth and crockery set elec fence post with 10 x 12 x 16 boulder on downhill size and trash (2647.9 W. Fraser record or 2573.7 or 74.2 N). Corner set almost exact to J. Kerr corner but the meas difference of 74.2 cant be overlooked.

4-20-1984 County Surveyor. Set telspar pipe over 3/8" iron set in April, 1972. The pipe was crushed on top from driving so did not use cap. RP Spike & CSD in 10" Elm SE 18.27.

12-6-2002 County Surveyor found square pipe up 1.5' in good condition.

12-9-2002 County Surveyor cut 1.0' off telspar pipe and removed 1/8" iron rod and set Cast Iron Cap on pipe up 0.5'. Checked spike and disc 18.22' SE.