Certificate of Location of Government Corner

ID#:531706 **Description:** 1/4 SEC COR 17 18 53 **Date Set:** 11/19/1997 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 13W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls on west side of N-S fence and 13 1/2' south of fence east
Bottle cap in W side 6" Eldeberry NNW 26.0'
Bottle cap in W side creosote brace post N 21.5'
Bottle cap in W side treated brace post NE 15.73'
Post w/sign 1/2' east
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes M.G. Karrick 40.00 set 1/4 section post. Bur Oak 16 S 38 W 132. Bur Oak 13 S 54 E 411.

5-1856 T. Hunter (P.4 No.6). Used corner set 1/16 cor North 20.07 2 B trees M & L. (N 86 1/2° W 249 links) & (S 78 1/4° E 302 links). Set 1/16 South 20.07 1/2 2 B trees M & L (N 69 1/2° W 139 links) & (N 69 3/4° E 75 links). Hunter (P.4 No.7 S.17) used corner meas North 40.14. Meas South 40.15. Meas East 39.73 (2622.18).

6-1886 T. Hunter (P411 No.400). Corner gone found 1/16 corners North and South (P.3 No.6). Set stake as 1/4 corner from these corners. Meas North and South to 1/16 corners 20.07 1324.62. Run and meas line from CIM at SE 18 North checking centerline road. Maybe likely post at 1/4 corner land always common on both sides and mostly terminal at 1/16 prop fences N of 1/4 17-18.

3-6-1973 County Surveyor dug 3' x 5' x 4' deep near computed M & L for 1/4 17-18 found definate post hole about 1' W 4' N set 6 long brush stick in hole. Set 1/2" x 2' pipe as near M & L. Transit area in deep was delta between 2 farms.

9-26-1996 County Surveyor found pipe set by R.B. in 1973 found by V.F. in 1996 1' SW of Cp to fence N-S-E. Will traverse to verify position before setting final corner.

9-27-1996 County Surveyor, after traverse, dug and dipped for pipe set by R.B. in 1973 13.07' South of pipe found by CP to fence N-S-E. We dug 2' deep in fence and burnt out roots and brush. We didn't get a dip or find rust. If this was a ditch area as stated by merrit P in 1973 it is hard to figure what went on here. The pipe by the CP is a 1/2" pipe with union on top 2' long. This area is a filter area from West.

10-1-1996 Vince Fangman set 30" telspar w/no cap as corner for survey in SE 1/4 section 18. RP's Nail and bottle cap in West side 6" Eldeberry NNW 26.00. Nail and bottle cap in West side creosoted brace post N 21.50. 1/2" pipe on West side C.P. fences N-S-E N 13.12 (removed). Nail and bottle cap West side treated brace post fence East NE 15.73. Vince set corner after county surveyor checked his traverse and discovered that the 1/2" pipe found by both vince and co. surv. to be too far North.

6-13-1997 County Surveyor found telspar set by V.F. in good condition at county surveyor established location. Set post and sign 1/2' E.

11-19-1997 County Surveyor set cast iron cap on telspar pipe in larger V. Fangman pipe as final corner West side N-S fence & 13 1/2' South of fence East.

6-20-2005 County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.