Certificate of Location of Government Corner

ID#: 531906 **Description:** W 1/4 SEC COR 19 53 **Date Set:** 10/18/2007 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 13W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1/2' west of centerline of CSAH 20, in centerline of CR 120 west and in line with fence east
The monument is at the surface
County Survey Disk in S side PP #50697 WNW 86.27'
County Survey Disk in NW side PP #50698 NE 92.08'
Ref pipe E 80.40'
This corner is located by GPS reference stations "Ref Pipe 531906 & Morlock"

Corner History:

8-12-1853 J. Ball, Deputy Surveyor, north between sections 19 & 24 40.00 chains, set quarter section post. RPs - 10" Bur Oak N 0°40' E 155 links (102.30'), 12" Bur Oak N 6 1/2° W 181 links (119.46')

6-26-1876 T. Hunter, County Surveyor, (Field Book 4, Pages 138-139) found stake not marked with NE bearing tree grubbed out. Set 18"x8"x4" stone with stake on east side in unrecorded survey. RP - 8" Oak S 69° W 53-1/2 links (35.31')

6-4-1886 T. Hunter, County Surveyor, (Field Book 14, Page 62) indicates corner in unrecorded survey

7-7-1938 County Highway Department (Bk. 103, Pg. 5) dug and found 4"x6"x18" limestone down 0.5'. Top was badly cracked. Stone falls in east track of road and 2' south of fence east. RPs - Nail in 5" Burr Oak on fence line NW 69.8', Nail in 15" Burr Oak E 46.6', Nail in FP SE 60.5'

11-1941 County Highway Department (Bk. 137, Pg. 57) found stone monument in intersection found previously during township road work. Ben Engle, who has lived here for 50 years or more, avers that he has seen the stone before and that his father had told him it was the 1/4 corner. RPs - Disc in FP WNW 87.3', Disc in TP WSW 102.6', Spike in oak stump E 46.65'

7-29-1964 J. Kerr, County Surveyor, dug and found stone with stake. Set Cast Iron Monument above stone and other objects. Corner falls 3' east of center line and in line with fence east. RPs - 3/4"x36" steel rod (up 6") under fence E 99.93', Disc in PP NE 38.65', Disc in PP NW 44.96', Disc in TP SW 54.84', Disc in old TP (CHD witness) WSW 102.6'

3-31-1967 County Highway Department (Bk. 323, Pg. 1) found and used CIM for CSAH 20 alignment at PI Sta. 105+31.5. RPs - Spike & Disc in Gate Post SE 45.55', Spike & Disc in TP SW 54.82', Spike & Disc in PP NE 38.65', Spike & Disc in Gate Post NW 80.03'

11-19-1987 County Highway Department found and used CIM for CSAH 20 alignment at PI Sta. 105+31.5

6-1-1989 County Survey Crew found CIM in good condition and referenced prior to road construction. Set reference pipe East 80.40' on line to plastic disk in PP #9589. RPs - Spike & Disc in Brace Pole SE 43.81', Spike & Disc in PP NE 45.38', Spike & Disc in stub PP SW 54.76'

10-17-1991 County Survey Crew set 1" square pipe w/cap at surface from transit ties (see card for ties) after road construction. Corner falls in line with fence east and in line of centerline of CR 120 running west.

1-18-2002 County Survey Crew found 1" square pipe w/cap at surface in good condition and measured its position using GPS.

3-14-2005 County Survey Crew found 1" square pipe w/cap at surface in good condition.

9-15-2006 County Survey Crew found 1" square pipe w/cap at surface in good condition.

6-1-2007 County Survey Crew found 1" square pipe w/cap at surface in good condition. Tied out corner for 2007 overlays.

8-29-2007 County Survey Crew removed 1" square pipe w/cap for 2007 overlays.

10-12-2007 County Survey Crew set pk nail at surface from GPS and traverse data after determining that monument set in 1991 was incorrect.

10-18-2007 County Survey Crew set 1" square pipe w/cap at surface over pk nail.

9-27-2012 County Survey Crew found 1" square pipe with cap in good condition.