Certificate of Location of Government Corner

ID#: 540204 **Description:** 1/4 SEC COR 2 11 54 **Date Set:** 4/6/2004 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

County highway disk in 12" Oak SE 9.5'
County highway disk in 12" Oak E 31.9'
County highway disk in 12" Oak S 25.8'
County highway disk in Oak NE 38.65'
Spike in 10" Oak SSE 56.0'
Post w/sign 2' east
This corner is located by GPS reference stations "Elder B & C"

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect post West on true line between sect 2 - 11 40.21 set 1/4 sect. post Burr Oak 10 in. NE 18 lks Burr Oak 10 in S 68 E 27 lks

2-1872 T. Hunter P 193 No. 204 corner gone. Identified 2 stumps 1 marked as bearing trees. Both brought point to one spot by bearing & distance. Assumed them to be correct trees. Found small jack oak with 4" of corner. Marked tree on N & S sides as corner. Meas. east 40.39 to stake reset by witness tree.

11-1887 T. Hunter P. 423 No. 412 found NE bearing tree standing (?) and stump of SE bearing tree. Also marked small jack oak tree p. 193. 16 west set stake M & L 20.16 N 89°40'W North set stake on line at 23.93 Conveying SE 1/4 of SW 1/4 Z and 17 rods north of NE 1/4 of SW 1/4. Meas north 39.36 to Cetner 2 corrected in 1876 p. 294.

11-1907 Ch. Armstrong P. 110B set iron pipe. 2 bearing trees. Doesn't mention corner at all. Only on plat, describes 1/16 corners. 16 east set 1-1/2"x30" iron pipe M & L 20.05, 16 west set poplar stake M & L 20.16 Kelly will set stone.

Iron pipe used many years as corner. A 3" pipe up 15" in woods. 9' north & 2.5' east of field fence corner. A better monument than CIM. 16 south 1/2" rod in N-S fence set M & L 1314.0, 16 west 1/2"x3' rod in open pasture in flood delta set M & L 1328.0 R 1330.56 lines fair with field fence some 156' more or less feet east - impossible to reference.

10-17-1962 county highway department found 1-1/2" pipe in fence corner. Rp's spike & disk in 12" oak SE 9.5', spike & disk in 12" oak E 31.9, Spike & disk in 12" oak S 25.8', Spike in oak NE 38.65', Spike in 10" oak SSE 56.0'.

9-19-1989 County Surveyor found iron pipe standing but leaning badly to E, top of pipe also mushroomed.

2-23-2004 County Surveyor found 3" pipe up 1.3' leaning east.

4-1-2004 1/16th north: County Surveyor found 2" pipe up 0.3' leaning 0.3'± west. Steel post 1/2' SE.

4-6-2004 County Surveyor found 3" pipe up 1.3' bent and leaning slightly east. Removed 3" pipe and set 6' telspar pipe w/cast iron cap up 0.3' at projected position of top of 3" pipe. Set post w/sign 2' east.