Certificate of Location of Government Corner

ID#: 540405 **Description:** SEC COR 4 5 8 9 54 **Date Set:** 6/12/2006 **County:** Olmsted

Section: 04 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in line with fence south, 1/2' north of centerline of E-W road and 24' west of centerline of field drive north
Steel fence post S 50.0'
This corner is located by GPS reference stations "CR 16 A & B"

Corner History:

1853 Gov't Notes; 80.0 set post for corner to section 4-5-8-9 in mound of earth, sod charcoal, trench, pits, and planted osage orange seed NW & SW.

5-1879 T. Hunter P.358 No.349 found stake remains in line old fence running south. Also pole by its side used to align fences set by landowners. Set stake foot below surface with boulder 4x10x20 on top stake. - 16 east set marked stake M & L 20.02-1/2. - meas. south to M & L 40.02-1/2.

8-1889 Thos. Fraser P.434 No.421 found stone in line fence south P. 359 5x12x16 - Meas west 39.77-1/2 (2625.15 to corner set M & L.

5-1896 T. Hunter P.601 No.546 found stone P.358 set new stone sandstone 7x8x20 with wide flange at bottom. - 16 east set boulder 7x7x16 M & L 20.03 - Meas. south 40.03 to stake with stone by side 1/4 8-9.

7-3-1961 county highway department found 8" x 8"x 8" Limestone with stake

8-1961 county highway department B222 8x8x8 limestone with stake replaced limestone & stake found with 8x8x30 conc. set monument, 1" rod riser. 16 east 1926 B38 P.153 steel fence post N 50.0 found 16 stone east. Steel fence post S 50.0 Sp. D pp SW 49.68. Hub SW 78.1 Hub SE 78.0

1964 J. Kerr found 1" rod center blacktop Meas. west to 1/4 5-8 2622.2 R 2625.15 - 1889

7-25-1972 County Surveyor found iron set by J. Kerr.

1982 County Surveyor found iron at road surface.

1-21-2004 County Surveyor found 1" steel rod down 0.3' in good condition.

4-26-2006 County Surveyor found 1" steel rod down 0.3'. Road is still intact but no longer being used.

5-18-2006 County Surveyor found 1" steel rod in good condition down 0.3' removed. Found 8x8 concrete monument down 1.6', ties matched.

6-12-2006 County Surveyor set a 1" square pipe w/cap #15809 at surface from 2004 construction tie out.