Certificate of Location of Government Corner

ID#: 540904 **Description:** 1/4 SEC COR 9 16 54 **Date Set:** 7/20/1972 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 10' west of centerline of twp road south and 2' north of centerline of twp road west
2 1/2" heavy angle iron CP (slope meas.) NE 52.22'
Steel post 1/2' west
Post w/sign 2' north
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect post, West in true line between sects 9 & 16. 40.10 set a 1/4 sect. Post in mound N 8°07'E of earth. Sod deposited charcoal made trench & pitts planted Osage orange seeds W & S

6-1872 T. Hunter BK. A pg. 207 found old stake and set a stone 5" by 8" by 18".

5-1879 Hunter BK. A pg. 358 found stone in the center of the road.

5-1896 Hunter BK. A pg. 601 corner gone, reset midway & on line at 2645.94'.

5-1957 K. McGhie set a 1 1/4" pipe midway and on line at 2647.5'.

8-10-1970 County Surveyor found pipe & rod inside bent over near centerline road west, near line edge road south - west edge, further RPs on airport guard road closed barricade steel posts 3-1/2" dia. +N side half way up NE 30.04, +S side half way up SE 32.23 will set CIM later as time permits.

7-20-1972 County Surveyor found McGhie pipe. Meas north to large 1/16 stone found at 1320.4 (R1318.35) - Con't meas to Center 9 stone found. (rough meas. Too far east for accuracy). Zaped line from N 1/4 9 over center (CIM set) 2639.49 (R2640), Zaped Center 9 to 1/16 stone 1318.03 (R1318.35) where stone was found to be .47 west of direct line. - Set stone on line, may still be hit by plow iron grate originally found 3' west of stone on N side of stone. - set CIM over 1/2" x 3' rod at double meas 1318.03 and on line run. - Zap S to stone at Center 16 2627.35 (R2620.02) (1872). Zap W to CIM and grate 2645.42 RH 1896. 1879. 40.09 2645.94 corner comes.85 W and 2.16 N of McGhie pipe. RPs to CIM as set. 40.15 SW to bottle cap in NW side PP #25051, 29.44 NNE to bottle cap on E side PP #25052, 52.13 NE on direct slope straight chain (plumb a little on CIM end because of edge road to top 2-1/2" heavy angle corner post. 30.55 due E to hard nail in top of bottom plank guards. Corner 2' N center main road west, 8' E center Main road S.

10-1982 County Surveyor found CIM in good condition.

Note: This is a correction of a corner set by K. McGhie. The reset corner set by me from the N by running the NS 1/4 line over the center and the sixteenth South and double the distance from the center of 9 to the sixteenth South at 1318.03'. The corner moved .85' West & 2.16' North of McGhie pipe.

10-11-1989 County Surveyor found CIM 6" below surface in Rd ditch RPs 52.22' SW of top of heavy angle iron CP (no longer used in fence). 44.66' W of conc. Nail in top of bottom board in "road closed" guard 10.0 W centerline road S, 2.0 N centerline road W.

1-21-2004 County Surveyor found CIM down 0.8' in good condition with steel post 0.5' west.

10-15-2007 County Surveyor found CIM down 0.7' in good condition. Set post w/sign.