Certificate of Location of Government Corner

ID#: 540905 **Description:** SEC COR 8 9 16 17 54 **Date Set:** 4/1/2004 **County:** Olmsted

Section: 09 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1/2' east of fence north, 1/2' west of fence south and 1' south of centerline of E-W twp road
1 1/4" x 26" tapered steel tube-up 3" under fence N 100.0'
Near side of heavy angle iron CP N 33.9'
This corner is located by GPS reference stations "WCF A & B"

Corner History:

1853 Gov't Notes Yerby 80.00 Set post for corner to sect. 8,9,16,17 in mound of earth & sod deposited charcoal made trench, pitts, planted Osage Orange seeds NE & SE.

6-1872 T. Hunter. Corner could not be found. Set stake with range of old fences set from original corner.

5-1879 T. Hunter p.358 No. 349 found stake set p. 215 - east 40.09 - north 40.02-1/2.

8-1889 Thos. Fraser P. 434 No. 421 found stake P.207 in center road, in line willows running north, set larger stake in place. - Meas. west to 39.58 3/4 2612.77 M & L stone 12 x 15 x 24 set.

5-1896 T. Hunter P.601 No.546 & others, corner stake gone, road freshly worked. Replaced corner from NW 9 over W 1/4 9 as in P. 358. Set stone at projected line and double dist. 40.03 comes in line fence north. - meas east 40.09 to corner reset M & L. - meas north 40.03 to corner set M & L p.358.

5-1957 McGhie iron grate 1-1/2" pipe east of corner. Sp corner fence post north 26.0, Sp corner fence post NE 41.4, Sp cor fence post S 27.3, Sp root of willow N 43.7

8-6-1970 County Surveyor found cast grate down 16". Set CIM over 1 1/2"x17" pipe below grate on east side.

7-20-1972 County Surveyor dug with backhoe from CIM north 4' W4' E4' found 18" rock fill over very wet subgrade but no stone deep black mark in clay. NE of CIM 2'± but nothing positive as similar grate (orig corner) was found (7-20-72) at 1/16 N of 1/4 9-16 at least 2 to 3 feet west of true stone found its may be grate at 8-9-16-17 also some incorrect, left CIM as is.

Fall, 1982 County Surveyor found CIM in good condition.

1-21-2004 County Surveyor found CIM down 0.4' leaning slightly NNE. Checked tie to fence post was within .02'. Shot distance to pipe to the north 99.93'.

4-1-2004 County Surveyor found CIM down 0.4'. Took local ties and removed. Found 1 1/2" pipe down 2.0' removed. Set 6' telspar pipe w/CIC down 0.5' at pipe location.