Certificate of Location of Government Corner

ID#: 541504 **Description:** 1/4 SEC COR 15 22 54 **Date Set:** 9/11/2006 **County:** Olmsted

Section: 15 **Township:** 105N **Range:** 14W **Monument Description:** 1" square pipe w/cap RLS #42638

Reference Ties:

The monument is down 0.4'
The corner falls 27' north of centerline of TH 30 and 5' west of centerline of driveway north
County highway disk in PP #9512 SE 147.75'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes Yerby 40.00 set temp 1/4 sect. post West on true line between sect. 15 & 22 40.22 set a 1/4 sect. post in mound V 7°58'E of earth & sod, deposited charcoal , made trench & pitts, planted Osage Orange seed N & S.

No records - MHD const. notes - assumed corner. inters. east-west fences - center between road fences north & south no station center highway as built about 27' south of corner which lies in service road north. Center trunk highway south S 27.0, Disc power pole NE 69.4, Disc power pole SE 147.7. Meas. west to section corner 2658.15, Meas. east to section corner 2651.7.

11-10-1964 County Surveyor found 1/2" x 30" steel rod located by MHD. Set CIM over 5/8"x12" rod.

1-21-2004 County survey crew found CIM in good condition down 0.8'.

4-3-2006 County survey crew found CIM down 0.8' in good condition.

9-5-2006 County survey crew found CIM in good condition down 0.8'.

9-7-2006 County survey crew found CIM in good condition down 0.8', took local ties and removed. Found iron rod in good condition down 2.5'.

9-11-2006 County survey crew set 1" square pipe w/cap from local ties taken from CIM at surface. Nail and disc in PP #9512 SE 147.75'.

4-25-2013 County survey crew found 1" square pipe at the surface. The existing cap was worn smooth so it was removed and replaced with a new cap #42638. Monument was lowered 0.4' for 2013 road overlay.