Certificate of Location of Government Corner

ID#: 541606 **Description:** 1/4 SEC COR 16 17 54 **Date Set:** 11/5/1982 **County:** Olmsted

Section: 16 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' east of N-S fence and 3' north of fence west
Concrete nail in N side fence post SW 4.21'
Spike in W side old fence post NW 4.75'
Post w/sign 1' west
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes William B. Yerby, Deputy Surveyor North between sections 16 and 17. 40.00 chs. Set a quarter section post in mound of earth and sod. Deposited charcoal. Made trench and pits. Planted Osage Orange seed East and West.

6-1872 Thomas Hunter, County Surveyor, (Book A, Page 207, No. 215, and Old Fieldbook 1, Page 35) "Found old stake in ground said to be in mound where old 1/4 stake stood, but no remains of mound left." He used the corner to set the 1/16 North, a stake, midway (19.80 chs.) and on line to the NW Cor. 16; and to set the 1/16 South, a stake, midway (19.90 1/2 chs.) and on line to the SW Cor. 16. He also set the 1/16 East, a stake, midway (19.98 1/2 chs.) and on line to the Center 16, a stone 4x5x12 inches set at intersecting 1/4 lines. He set the 1/16 East of the Center 16, a short stake in center of road, midway (19.98 chs.) and on line to the E 1/4 Cor. 16, a stake found.

10-8-1982 County Surveyor found after measuring between Hunter's corners found or reset in Section 16 that we overrun his measurements at an average of 8.6 per 1/2 mile; however, our measurement from the NW Cor. 16 to the corner post at 1/4 Cor. 16-17 overruns Hunter by 12.1 feet, so we dug on the North side of the corner post and 1' East and 3' North we found a 1' square mark running down into clay subsoil. Found nothing further.

11-5-1982 County Surveyor dug at the E 1/4 Cor. 16 but could not find corner (See Cert. Filed). Accepted mark found 10-8-1982 as location of Hunter's corner at 1/4 Cor. 16-17 and set a Cast Iron Monument over a 1/2"x16" re-rod as the corner at its location.

7-20-2004 County Surveyor found CIM down 0.5' in good condition.