Certificate of Location of Government Corner

ID#: 542304 **Description:** 1/4 SEC COR 23 26 54 **Date Set:** 1/23/2002 **County:** Olmsted

Section: 23 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of CR 120 and 69.2' north of bridge deck
County Survey Disk in S side PP #38876 E 50.12'
Ref pipe W 116.62'
Chisled X in NW wingwall of bridge SW 73.35'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes W.B. Yerby, Deputy Surveyor. West on true line between sections 23 and 26. 40.10 chs. Set a quarter section post in mound of earth and sod and deposited charcoal. Made trench and pits and planted osage orange seed north and south of trench.

6-1899 William Fraser, County Surveyor, corner lost. Set stake midway and on line 40.155 chs. (2650.23').

1906 Charles Armstrong (Book B P.108-109), County Surveyor, in plat of Sec. 26 shows stone as N 1/4 26 with 1/16 corner stakes West and South.

7-23-1974 County Surveyor reset a CIM over a 3/4"x8" rod midway and on line at 2651.78' by electronic traverse.

3-24-1981 County Surveyor found CIM with head broken off. Referenced corner before road grading. RP- 1" square pipe w/cap 116.62 W and on line to a PK in fence post 94.70 W of the 1" square pipe. Put a survey marker sign & post .5' north of the 1" square pipe.

4-23-1996 County Surveyor found P.K. Nail at surface of crushed rock CR 120 set from 1981 reference pipe. Found pipe 9" deep that fit 1981 references. Put plastic cap #15809 in pipe. RPs- CSD in PP #38876 E 50.07', N end conc. Bridge S 69.2'.

2-17-1998 County Surveyor found 1" pipe down 0.8' in CR 120 in good condition.

1-23-2002 County Surveyor replaced 1" pipe with 3' telspar pipe with cast iron cap down 0.6'.