Certificate of Location of Government Corner

ID#: 542806 **Description:** 1/4 SEC COR 28 29 54 **Date Set:** 7/9/2002 **County:** Olmsted

Section: 28 **Township:** 105N **Range:** 14W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 6' south of centerline of E-W twp road, 13' west of fence north and in line with fence south
16d nail in E side CP S 26.34'
Center of No. plate in PP #11402 WSW 74.83'
SE corner concrete house foundation NW 137.15'
This corner is located by GPS measurement

Corner History:

1853 Gov't notes, Yerby; 40.0 set a 1/4 section post. RPs- 12" burr oak N7 W333 links, 4" burr oak N38 E66 links.

1892 Tom. Fraser (BK. A pg. 491) reset the corner with a boulder stone.

7-19-1971 County Surveyor set CIM over cross on boulder and 1" pipe. RPs- Sykes corner 25.8 SW to pepsi cap on W side pp at base, #11405 plimbed 3 to avoid leaning pole, 47.62 N to Fresa cap on top 4" cedar corner post, 98.9 NE to center tele cable post, 147.0 ESE to center PP #11405, pipe as corner 4.5 S center road & 3' E fence line N±. RPs CIM 1/4 28-29- 26.34 S to 16D on E side corner post, 60.04 NW to SW edge square mailbox post, 67.41 SSW to 40D in root E side 24" long chinese elm, 74.83 WSW to center no plate of PP with trans #11402, 137.15 NW to SE corner poured house foundation.

6-1975 County Surveyor found top of CIM had been broken off. Removed top and left remainder as corner.

NOTE: MHD R/W map & (field notes researched 1-9-1978 RB) shows stone (found) at intersection of fe and road. I believe that this stone was incorrect as McGhie & Betts, Inc. in Jan. 1978 find that angle to I-90 & meas. to this 1/4 corner to be incorrect. RB 1-9-1978.

6-19-2002 County Surveyor found CIM w/head broken off.

7-9-2002 County Surveyor removed broken CIM and set 5' telspar pipe w/Cast Iron Cap.

9-27-2006 County Surveyor found cast iron cap on telspar pipe down 0.4' in good condition.